


Display CARFAX in online listings: ☐




This report provided free of charge by:

Van Bortel Ford
71 Marsh Rd
East Rochester, NY 14445
585-460-1438

5X TOP-RATED DEALER

★ **4.8 / 5.0**
1,425 Verified Reviews

♥ **9,807**
Customer Favorites



Vehicle History Report™

US \$44.99

2010 SUBARU OUTBACK 2.5I PREMIUM
VIN: 4S4BRBCC4A3367883
4 DOOR WAGON/SPORT UTILITY
2.5L H4 F SOHC 16V GASOLINE
ALL WHEEL DRIVE
This CARFAX Report Provided by:
Van Bortel Ford
★ **4.8 / 5.0**
1,425 Verified Reviews
♥ **9,807** Customer Favorites

✓ No accidents or damage reported to CARFAX

🔧 41 Service history records


👤 2 Previous owners

🏠 Personal vehicle



🌐 Last owned in New York


📊 92,313 Last reported odometer reading





This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/13/24 at 3:54:26 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.














<div> Additional History Not all accidents / issues are reported to CARFAX</div>	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported
Structural Damage No structural damage reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated	✓ No Issues Indicated






Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired






 Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate		

 Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2010	2018
Type of owner	Personal	Personal
Estimated length of ownership	7 yrs. 9 mo.	6 years
Owned in the following states/provinces	New York	New York
Estimated miles driven per year	3,717/yr	10,621/yr
Last reported odometer reading	29,357	92,313

 Detailed History				
<div>  Owner 1 Purchased: 2010 </div> <div>  </div> <div> Low mileage! This owner drove less than the industry average of 15,000 miles per year. </div> <div> Personal Vehicle 3,717 mi/yr </div>				
Date	Mileage	Source	Comments	
04/16/2010	6	Van Bortel Subaru Victor, NY 585-924-5230	 Vehicle serviced - Pre-delivery inspection completed - Safety inspection performed	

		vanbortelsubaru.com  4.8 / 5.0 157 Verified Reviews  7 Customer Favorites	-Emissions or safety inspection performed
04/16/2010		New York Inspection Station	Emissions inspection performed - Passed safety inspection
04/20/2010		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 157 Verified Reviews  7 Customer Favorites	Vehicle sold
04/20/2010		New York Motor Vehicle Dept. Webster, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
05/26/2010		New York Motor Vehicle Dept. Webster, NY	Title issued or updated - First owner reported - Titled or registered as personal vehicle
10/07/2010	1,739	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 157 Verified Reviews  7 Customer Favorites	 Vehicle serviced - Oil and filter changed
04/18/2011	4,108	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 157 Verified Reviews  7 Customer Favorites	 Vehicle serviced - Tires rotated - Oil and filter changed - Safety inspection performed
04/18/2011		New York Inspection Station	Emissions inspection performed - Passed safety inspection
09/27/2011	6,518	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 157 Verified Reviews  7 Customer Favorites	 Vehicle serviced - Oil and filter changed
03/14/2012		New York	Registration issued or renewed

		Motor Vehicle Dept. Webster, NY		- Titled or registered as personal vehicle - Passed safety inspection
04/10/2012	8,588	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Safety inspection performed - Oil and filter changed - Emissions inspection performed
04/10/2012		New York Inspection Station		Passed safety inspection - Passed emissions inspection
11/30/2012	11,400	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Air filter replaced - Oil and filter changed
04/03/2013	12,257	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Safety inspection performed - Oil and filter changed - Emissions inspection performed
04/03/2013		New York Inspection Station		Passed safety inspection - Passed emissions inspection
12/04/2013	16,444	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Oil and filter changed
03/18/2014		New York Motor Vehicle Dept. Webster, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
04/22/2014	18,184	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Oil and filter changed - Safety inspection performed

04/22/2014	18,185	New York Inspection Station	Passed safety inspection - Emissions inspection performed
12/05/2014	21,516	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Oil and filter changed
05/04/2015	22,416	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Safety inspection performed - Air filter replaced - Oil and filter changed - Two tires balanced - Tires rotated - Emissions inspection performed
05/04/2015		New York Inspection Station	Passed safety inspection - Passed emissions inspection
11/23/2015	23,771	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Oil and filter changed
03/16/2016		New York Motor Vehicle Dept. Webster, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
05/13/2016	24,388	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked - Safety inspection performed - Emissions inspection performed
05/13/2016		New York Inspection Station	Passed safety inspection - Passed emissions inspection
06/07/2017	27,060	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews	 Vehicle serviced - Safety inspection performed - Oil and filter changed - Light bulb(s) replaced - Emissions inspection performed

♥ 7 Customer Favorites

06/07/2017

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

01/26/2018

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

Vehicle offered for sale

★ 4.8 / 5.0

157 Verified Reviews

♥ 7 Customer Favorites

01/26/2018 28,905

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Pre-delivery inspection completed
- Wiper(s) replaced
- Air filter replaced
- Front brake rotor(s) replaced
- Front brake pads replaced
- Rear brake pads replaced
- Brake rotor(s) replaced
- Four wheel alignment performed
- Four tires mounted
- Cabin air filter replaced/cleaned
- Emissions or safety inspection performed

★ 4.8 / 5.0

157 Verified Reviews

♥ 7 Customer Favorites



Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

02/02/2018 28,963

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

02/05/2018

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

Vehicle sold

★ 4.8 / 5.0

157 Verified Reviews

♥ 7 Customer Favorites

02/05/2018

New York
Motor Vehicle Dept.
Canandaigua, NY

Registration issued or renewed
- Titled or registered as personal vehicle
- Passed safety inspection

02/22/2018 29,357

XL Auto Service & Tires
Canandaigua, NY
585-396-2610
xlautony.com



Vehicle serviced

★ 5.0 / 5.0

39 Verified Reviews

♥ 7 Customer Favorites







Owner 2


Purchased: 2018
























Low mileage! This owner drove less than the industry average of 15,000 miles per year.







Personal Vehicle
10,621 mi/yr





Date	Mileage	Source	Comments
02/23/2018		New York Motor Vehicle Dept. Canandaigua, NY	Title issued or updated - New owner reported
04/13/2018		New York Motor Vehicle Dept. Canandaigua, NY	Registration issued or renewed - Correction to record - Titled or registered as personal vehicle - Passed safety inspection
04/24/2018	30,942	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed
07/28/2018	34,723	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed
01/28/2019	40,129	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Oil and filter changed - Emissions inspection performed
01/28/2019		New York Inspection Station	Passed safety inspection - Passed emissions inspection
04/29/2019	43,418	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed

 7 Customer Favorites

06/20/2019		New York Motor Vehicle Dept. Canandaigua, NY		Registration issued or renewed <ul style="list-style-type: none">- Titled or registered as personal vehicle- Passed safety inspection
07/29/2019	48,126	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 157 Verified Reviews  7 Customer Favorites		Vehicle serviced <ul style="list-style-type: none">- Maintenance inspection completed- Oil and filter changed- Air filter replaced- Front wiper blades/refills replaced
10/28/2019	51,628	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 157 Verified Reviews  7 Customer Favorites		Vehicle serviced <ul style="list-style-type: none">- Maintenance inspection completed- Rear wiper blade replaced- Tire(s) balanced- Tires rotated- Oil and filter changed
01/30/2020		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 157 Verified Reviews  7 Customer Favorites		Vehicle serviced <ul style="list-style-type: none">- Oil and filter changed- Emissions or safety inspection performed
01/30/2020	54,736	New York Inspection Station		Passed safety inspection <ul style="list-style-type: none">- Passed emissions inspection
02/10/2020	55,157	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 157 Verified Reviews  7 Customer Favorites		Vehicle serviced
05/29/2020	58,150	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 157 Verified Reviews  7 Customer Favorites		Vehicle serviced <ul style="list-style-type: none">- Oil and filter changed
11/05/2020	64,109	Van Bortel Subaru Victor, NY 585-924-5230		Vehicle serviced <ul style="list-style-type: none">- Maintenance inspection completed- Tire(s) balanced

		vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	- Tire(s) mounted - Oil and filter changed
01/11/2021	65,780	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Emissions or safety inspection performed
01/11/2021	65,781	New York Inspection Station	Passed safety inspection - Passed emissions inspection
02/17/2021	66,519	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced
06/01/2021	69,153	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Oil and filter changed
07/02/2021		New York Motor Vehicle Dept. Canandaigua, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
08/04/2021	70,897	XL Auto Service & Tires Canandaigua, NY 585-396-2610 xlautony.com ★ 5.0 / 5.0 39 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Brake calipers cleaned/serviced - Front brake pads replaced - Front brake rotor(s) replaced - Brakes checked
08/31/2021		XL Auto Service & Tires Canandaigua, NY 585-396-2610 xlautony.com ★ 5.0 / 5.0 39 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Brake light bulb(s) replaced

09/13/2021	71,889	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Oil and filter changed
01/12/2022	75,018	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced
01/12/2022		New York Inspection Station	Passed safety inspection - Passed emissions inspection
03/24/2022	76,611	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Oil and filter changed
06/21/2022	78,914	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Tires rotated - Oil and filter changed - Brakes checked
09/20/2022	81,136	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Oil and filter changed
12/15/2022	83,461	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Tires rotated - Oil and filter changed - Wiper(s) replaced - Emissions or safety inspection performed

12/15/2022		New York Inspection Station		Passed safety inspection - Passed emissions inspection
03/28/2023	85,836	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Oil and filter changed
06/09/2023		New York Motor Vehicle Dept. Canandaigua, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
07/13/2023	88,279	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Oil and filter changed
11/30/2023	91,414	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Emissions or safety inspection performed
11/30/2023		New York Inspection Station		Passed safety inspection - Passed emissions inspection
02/01/2024	92,313	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Brakes checked - Rear brake pads replaced - Rear brake rotor(s) replaced - Brake rotor(s) replaced - Rear brakes replaced - Drive belts checked - Timing belt replaced - Brake line(s) replaced/repared - Subframe repaired/replaced - Oil and filter changed

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
3/13/24 3:54:26 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2010 SUBARU OUTBACK vehicle (VIN: 4S4BRBCC4A3367883), which is based on information supplied to CARFAX and available as of 3/13/24 at 4:54 PM (EDT).

Customer Signature

Date

Dealer Signature

Date