


Display CARFAX in online listings: ☐




This report provided free of charge by:

Van Bortel Ford
71 Marsh Rd
East Rochester, NY 14445
585-460-1438

5X TOP-RATED DEALER

★ **4.8 / 5.0**
1,425 Verified Reviews

♥ **9,801**
Customer Favorites





Vehicle History Report™


US \$44.99


**2014 SUBARU
OUTBACK 2.5I
PREMIUM**
VIN: 4S4BRBDC7E3250562
4 DOOR WAGON/SPORT
UTILITY
2.5L H4 F DOHC 16V
GASOLINE
ALL WHEEL DRIVE
This CARFAX Report Provided
by:
Van Bortel Ford
★ **4.8 / 5.0**
1,425 Verified Reviews
♥ **9,801** Customer Favorites


Damage reported: minor damage




MINOR MODERATE SEVERE



 **7** Service history records

 **CARFAX 1-Owner vehicle**

 **Personal vehicle**

 **152,440** Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/12/24 at 2:05:25 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

<div> Ownership History The number of owners is estimated</div>		Owner 1
Year purchased		2014
Type of owner		Personal
Estimated length of ownership		10 yrs. 2 mo.
Owned in the following states/provinces		New York
Estimated miles driven per year		14,869/yr
Last reported odometer reading		152,440

<div> <div>CARFAX</div> <div>Title History</div> </div> <div>CARFAX guarantees the information in this section</div>	<div>Owner 1</div>
<div>Damage Brands</div> <div>Salvage Junk Rebuilt Fire Flood Hail Lemon</div>	<div> <div>✓</div> <div>Guaranteed No Problem</div> </div>
<div>Odometer Brands</div> <div>Not Actual Mileage Exceeds Mechanical Limits</div>	<div> <div>✓</div> <div>Guaranteed No Problem</div> </div>
<div> <div> <div>BUYBACK</div> <div>CARFAX</div> <div>GUARANTEE</div> </div> <div> <div>GUARANTEED</div> <div>- None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.</div> <div>View Terms View Certificate</div> </div> </div>	


<div> <div>CARFAX</div> <div>Additional History</div> </div> <div>Not all accidents / issues are reported to CARFAX</div>	<div>Owner 1</div>
<div>Total Loss</div> <div>No total loss reported to CARFAX.</div>	<div> <div>✓</div> <div>No Issues Reported</div> </div>
<div>Structural Damage</div> <div>CARFAX recommends that you have this vehicle inspected by a collision repair specialist.</div>	<div> <div>✓</div> <div>No Issues Reported</div> </div>
<div>Airbag Deployment</div> <div>No airbag deployment reported to CARFAX.</div>	<div> <div>✓</div> <div>No Issues Reported</div> </div>
<div>Odometer Check</div> <div>No indication of an odometer rollback.</div>	<div> <div>✓</div> <div>No Issues Indicated</div> </div>
<div>Accident / Damage</div> <div>Damage reported: 02/15/2021.</div>	<div>Minor Damage</div>
<div>Manufacturer Recall</div> <div>Check with an authorized Subaru dealer for any open recalls.</div>	<div> <div>✓</div> <div>No Recalls Reported</div> </div>
<div>Basic Warranty</div> <div>Original warranty estimated to have expired.</div>	<div>Warranty Expired</div>

CARFAX

Detailed History

Owner 1

Purchased: 2014



Low mileage!

This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle

14,869 mi/yr

Date	Mileage	Source	Comments
11/14/2013		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com	Vehicle offered for sale

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

12/05/2013 15

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Pre-delivery inspection completed
- Emissions or safety inspection performed

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

12/06/2013

New York
Inspection Station

Passed safety inspection

- Emissions inspection performed

12/07/2013

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

Vehicle sold

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

01/02/2014

New York
Motor Vehicle Dept.
Livonia, NY

Title issued or updated

- Registration issued or renewed
- First owner reported
- Titled or registered as personal vehicle
- Loan or lien reported
- Passed safety inspection

05/10/2014 7,625

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Oil and filter changed

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

12/06/2014 18,067

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Safety inspection performed
- Oil and filter changed
- Emissions inspection performed

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

12/06/2014

New York
Inspection Station

Passed safety inspection



- Passed emissions inspection


01/30/2015

New York
Motor Vehicle Dept.
Livonia, NY


Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

01/05/2016	36,547	New York Inspection Station	Passed safety inspection - Passed emissions inspection
01/23/2017		New York Motor Vehicle Dept. Conesus, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection - Registration updated when owner moved the vehicle to a new location
02/13/2017	57,412	New York Inspection Station	Passed safety inspection - Passed emissions inspection
02/27/2018	76,788	New York Inspection Station	Passed safety inspection - Passed emissions inspection
01/31/2019		New York Motor Vehicle Dept. Conesus, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection - Registration updated when owner moved the vehicle to a new location
03/05/2019	96,535	New York Inspection Station	Passed safety inspection - Passed emissions inspection
04/22/2019		Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 137 Verified Reviews ❤️ 14 Customer Favorites	 Vehicle serviced - Inspection performed - Tire checked
04/30/2020	112,889	New York Inspection Station	Passed safety inspection - Passed emissions inspection
12/22/2020		New York Motor Vehicle Dept. Conesus, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection - Registration updated when owner moved the vehicle to a new location
02/15/2021		Damage Report	 Damage reported: minor damage - Damage to right side





Damage Location



CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

05/03/2021	122,979	New York Inspection Station	Passed safety inspection - Passed emissions inspection
05/25/2022	129,857	New York Inspection Station	Passed safety inspection - Passed emissions inspection
01/10/2023		New York Motor Vehicle Dept. Conesus, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection - Registration updated when owner moved the vehicle to a new location
04/07/2023	140,324	Scorsone's Service Center Geneseo, NY 585-243-2596 scorsones.com ★ 5.0 / 5.0 17 Verified Reviews ❤️ 1 Customer Favorite	 Vehicle serviced - Four tires balanced - Four tires mounted - Safety inspection performed - Oil and filter changed - Four tires replaced - Emissions inspection performed
04/07/2023		New York Inspection Station	Passed safety inspection - Passed emissions inspection
12/05/2023	148,613	Scorsone's Service Center	 Vehicle serviced - Oil and filter changed

Geneseo, NY
585-243-2596
scorsones.com

★ 5.0 / 5.0

17 Verified Reviews

♥ 1 Customer Favorite

- Four tires balanced

03/06/2024 152,440

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

137 Verified Reviews

♥ 14 Customer Favorites



Vehicle serviced

- Four tires balanced

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/12/24 at 2:05:25 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
3/12/24 2:05:25 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2014 SUBARU OUTBACK vehicle (VIN: 4S4BRBDC7E3250562), which is based on information supplied to CARFAX and available as of 3/12/24 at 3:05 PM (EDT).

Customer Signature	Date	Dealer Signature	Date
--------------------	------	------------------	------