


Display CARFAX in online listings: ☐




This report provided free of charge by:

Van Bortel Ford
71 Marsh Rd
East Rochester, NY 14445
585-460-1438

5X TOP-RATED DEALER

★ **4.8 / 5.0**
1,425 Verified Reviews

♥ **9,801**
Customer Favorites




Vehicle History Report™

US \$44.99

**2018 SUBARU
OUTBACK 2.5I
PREMIUM**
VIN: 4S4BSACCXJ3282366
4 DOOR WAGON/SPORT
UTILITY
2.5L H4 F SOHC 16V
GASOLINE
ALL WHEEL DRIVE
This CARFAX Report Provided
by:
Van Bortel Ford
★ **4.8 / 5.0**
1,425 Verified Reviews
♥ **9,801** Customer Favorites


Accident reported: minor damage





MINOR


MODERATE

SEVERE






 **7** Service history records

 **CARFAX 1-Owner vehicle**



 **Personal vehicle**


 **129,515** Last reported odometer reading




This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/12/24 at 2:33:05 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

| <div> Additional History</div> <div>Not all accidents / issues are reported to CARFAX</div> | Owner 1 |
|---|---|
| Total Loss No total loss reported to CARFAX. |  No Issues Reported |
| Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist. |  No Issues Reported |
| Airbag Deployment No airbag deployment reported to CARFAX. |  No Issues Reported |
| Odometer Check No indication of an odometer rollback. |  No Issues Indicated |


| | |
|--|---|
| Accident / Damage Accident reported: 10/06/2022. | Minor Damage |
| Manufacturer Recall Check with an authorized Subaru dealer for any open recalls. | <input checked="" type="checkbox"/> No Recalls Reported |
| Basic Warranty Original warranty estimated to have expired. | Warranty Expired |

| | |
|---|---|
|  Title History CARFAX guarantees the information in this section | Owner 1 |
| Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon | <input checked="" type="checkbox"/> Guaranteed No Problem |
| Odometer Brands Not Actual Mileage Exceeds Mechanical Limits | <input checked="" type="checkbox"/> Guaranteed No Problem |
|  GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate | |

| | |
|---|--------------|
|  Ownership History The number of owners is estimated | Owner 1 |
| Year purchased | 2018 |
| Type of owner | Personal |
| Estimated length of ownership | 6 yrs. 1 mo. |
| Owned in the following states/provinces | New York |
| Estimated miles driven per year | 22,881/yr |
| Last reported odometer reading | 129,515 |

| | | | |
|---|----------------|--|---------------------------------|
|  Detailed History | | | |
|  Owner 1 Purchased: 2018 | | Personal Vehicle 22,881 mi/yr | |
| Date | Mileage | Source | Comments |
| 12/28/2017 | | Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 | Vehicle offered for sale |

157 Verified Reviews


 7 Customer Favorites

12/30/2017 8

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Pre-delivery inspection completed
- Emissions or safety inspection performed

01/02/2018

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites

Vehicle sold

01/02/2018

New York
Inspection Station

Passed safety inspection

- Emissions inspection performed

01/29/2018

New York
Motor Vehicle Dept.
Auburn, NY

Title issued or updated

- Registration issued or renewed
- First owner reported
- Titled or registered as personal vehicle
- Loan or lien reported
- Passed safety inspection

08/02/2018 18,006

Fox Toyota Subaru
Auburn, NY
315-253-7341
foxtoyotasubaru.com

★ 4.6 / 5.0

151 Verified Reviews



Vehicle serviced

- Wheels checked

01/25/2019 32,083

New York
Inspection Station

Passed safety inspection


- Emissions inspection performed

03/04/2020 58,280

Dunn Tire
Auburn, NY
315-258-8281
dunntire.com

★ 4.9 / 5.0

80 Verified Reviews

 24 Customer Favorites



Vehicle serviced

- Tire(s) replaced
- Four tires replaced
- Alignment checked

03/04/2020

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

09/21/2020 68,475

Valvoline Instant Oil
Change
Auburn, NY



Vehicle serviced

- Oil and filter changed

315-253-0028

vioc.com

★ 4.7 / 5.0

132 Verified Reviews

♥ 185 Customer Favorites

05/12/2021 79,524

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

09/01/2021

New York
Motor Vehicle Dept.
Auburn, NY

Registration issued or renewed
- Titled or registered as personal vehicle
- Passed safety inspection

10/01/2021 84,763

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced
- Maintenance inspection completed

★ 4.8 / 5.0

157 Verified Reviews

♥ 7 Customer Favorites

06/20/2022 100,642

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

10/06/2022

Damage Report




Accident reported: minor damage with another motor vehicle
- Damage to right rear




**CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION**

Damage Severity Scale



Damage Location





Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

01/14/2023 112,427 Valvoline Instant Oil Change
Auburn, NY
315-253-0028
vioc.com
★ 4.7 / 5.0
132 Verified Reviews
❤️ 185 Customer Favorites



Vehicle serviced
- Oil and filter changed

04/27/2023 120,219 Valvoline Instant Oil Change
Auburn, NY
315-253-0028
vioc.com
★ 4.7 / 5.0
132 Verified Reviews
❤️ 185 Customer Favorites



Vehicle serviced
- Oil and filter changed
- Air filter replaced

08/30/2023 129,515 New York Inspection Station
Passed safety inspection
- Passed emissions inspection

08/30/2023 New York Motor Vehicle Dept.
Auburn, NY
Registration issued or renewed
- Titled or registered as personal vehicle
- Passed safety inspection

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/12/24 at 2:33:05 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
3/12/24 2:33:05 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2018 SUBARU OUTBACK vehicle (VIN: 4S4BSACCXJ3282366), which is based on information supplied to CARFAX and available as of 3/12/24 at 3:33 PM (EDT).

Customer Signature

Date

Dealer Signature

Date