Display CARFAX in online listings:



This report provided free of charge by:

Van Bortel Ford

71 Marsh Rd East Rochester, NY 14445

585-460-1438

5X TOP-RATED DEALER

± 4.8 / 5.0

1.413 Verified Reviews

9,766 **Customer Favorites**

Vehicle History Report™

US \$44.99

2011 SUBARU IMPREZA 2.5I PREMIUM

VIN: JF1GE6B6XBH522195 SEDAN 4 DR 2.5L H4 F SOHC 16V GASOLINE ALL WHEEL DRIVE

This CARFAX Report Provided

Van Bortel Ford

4.8 / 5.0

1,413 Verified Reviews



9,766 Customer Favorites



No accidents or damage reported to CARFAX



32 Service history records



2 Previous owners



Personal vehicle



Last owned in New York

109,989 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/28/24 at 12:47:08 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2011	2022
Type of owner	Personal	Personal
Estimated length of ownership	10 yrs. 5 mo.	1 yr. 11 mo.
Owned in the following states/provinces	New York	New York
Estimated miles driven per year	10,002/yr	2,550/yr
Last reported odometer reading	105,176	109,989

CARFAX Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem	Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem	Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms | View Certificate

CARFAX Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	No Issues Reported	No Issues Reported
Structural Damage No structural damage reported to CARFAX.	No Issues Reported	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported	No Issues Reported
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	No Recalls Reported	No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

CARFAX

Detailed History



Owner 1

Purchased: 2011



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle 10,002 mi/yr

Date Mileage Source Comments

08/29/2011 Van Bortel Subaru

Victor, NY 585-924-5230

vanbortelsubaru.com

Vehicle offered for sale

		★ 4.8 / 5.0 156 Verified Reviews ▼ 7 Customer Favorites		
08/30/2011	229	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 156 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Pre-delivery inspection completed - Emissions or safety inspection performed
08/30/2011		New York Inspection Station		Passed safety inspection - Emissions inspection performed
08/31/2011		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 156 Verified Reviews ▼ 7 Customer Favorites		Vehicle sold
09/30/2011		New York Motor Vehicle Dept. Amsterdam, NY		Title issued or updated - Registration issued or renewed - First owner reported - Titled or registered as personal vehicle - Loan or lien reported - Passed safety inspection
09/12/2012	9,738	New York Inspection Station		Passed safety inspection - Emissions inspection performed
12/28/2012	13,132	Capitaland Motors Inc. Schenectady, NY 518-399-9999 capitaland.net ★ 4.7 / 5.0 636 Verified Reviews ▼ 5,909 Customer Favorites	*	Vehicle serviced - Engine/powertrain computer/module reprogrammed
07/18/2013		New York Motor Vehicle Dept. Amsterdam, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
08/20/2013	21,134	New York Inspection Station		Passed safety inspection - Passed emissions inspection
02/06/2014	25,172	Capitaland Motors Inc. Schenectady, NY 518-399-999 capitaland.net	×	Vehicle serviced - Engine checked

		4.7 / 5.0 636 Verified Reviews Customer Favorites		
02/17/2014	25,579	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 156 Verified Reviews ▼ 7 Customer Favorites	*	Vehicle serviced
08/25/2014	34,871	New York Inspection Station		Passed safety inspection - Passed emissions inspection
11/28/2014	39,490	Capitaland Motors Inc. Schenectady, NY 518-399-9999 capitaland.net	*	Vehicle serviced
01/16/2015	41,033	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m ★ 4.7 / 5.0 22 Verified Reviews	*	Vehicle serviced - Oil and filter changed
07/23/2015		New York Motor Vehicle Dept. Amsterdam, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
08/13/2015	48,445	New York Inspection Station		Passed safety inspection - Passed emissions inspection
08/22/2015	48,824	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m ★ 4.7 / 5.0 22 Verified Reviews	*	Vehicle serviced
10/12/2015	51,253	Walmart Auto Care Center Amsterdam, NY 518-843-6899	×	Vehicle serviced - Tire(s) balanced - Tire(s) replaced

		https://www.walmart.com 4.7 / 5.0 22 Verified Reviews		
12/21/2015	53,720	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m ★ 4.7 / 5.0 22 Verified Reviews	*	Vehicle serviced - Oil and filter changed
05/05/2016	57,034	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m ★ 4.7 / 5.0 22 Verified Reviews	*	Vehicle serviced - Oil and filter changed
08/25/2016	60,211	Inspection Co.		Inspection performed
08/30/2016	61,685	New York Inspection Station		Passed safety inspection - Passed emissions inspection
04/13/2017	67,882	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m ★ 4.7 / 5.0 22 Verified Reviews	*	Vehicle serviced - Tires rotated
08/21/2017		New York Motor Vehicle Dept. Amsterdam, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
08/29/2017	71,882	New York Inspection Station		Passed safety inspection - Passed emissions inspection
09/08/2017	72,095	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m ★ 4.7 / 5.0 22 Verified Reviews	*	Vehicle serviced - Headlight(s) replaced

12/07/2017	74,115	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m ★ 4.7 / 5.0 22 Verified Reviews	*	Vehicle serviced - Tires rotated - Oil and filter changed
03/15/2018	76,282	Capitaland Motors Inc. Schenectady, NY 518-399-9999 capitaland.net	*	Vehicle serviced
07/11/2018	81,531	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m ★ 4.7 / 5.0 22 Verified Reviews	*	Vehicle serviced - Tire(s) balanced - Tires rotated
08/27/2018	82,460	Capitaland Motors Inc. Schenectady, NY 518-399-9999 capitaland.net ★ 4.7 / 5.0 636 Verified Reviews Customer Favorites	*	Vehicle serviced - Maintenance inspection completed
09/11/2018	82,579	New York Inspection Station		Passed safety inspection - Passed emissions inspection
01/16/2019	84,760	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m ★ 4.7 / 5.0 22 Verified Reviews	*	Vehicle serviced
04/02/2019	86,545	Capitaland Motors Inc. Schenectady, NY 518-399-9999 capitaland.net	*	Vehicle serviced

		5,909 Customer Favorites		
04/30/2019	87,486	Capitaland Motors Inc. Schenectady, NY 518-399-9999 capitaland.net 4.7 / 5.0 636 Verified Reviews 5,909 Customer Favorites	×	Vehicle serviced - Brake light switch replaced
05/17/2019	88,241	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m ★ 4.7 / 5.0 22 Verified Reviews	×	Vehicle serviced - Tires rotated
06/25/2019	90,427	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 136 Verified Reviews ■ 14 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Light bulb(s) replaced - Tire(s) balanced - Battery/charging system checked - Air filter replaced - Oil and filter changed - Brake fluid flushed/changed - Tire pressure sensor reprogrammed
07/16/2019		New York Motor Vehicle Dept. Amsterdam, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
08/07/2019	91,483	New York Inspection Station		Passed safety inspection - Passed emissions inspection
09/06/2019	92,392	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m ★ 4.7 / 5.0 22 Verified Reviews	*	Vehicle serviced - Headlight(s) replaced
12/03/2019	94,641	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m 4.7 / 5.0	*	Vehicle serviced - Tire(s) replaced - Tire(s) balanced

			22 Verified Reviews		
C	08/20/2020	97,610	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 136 Verified Reviews 14 Customer Favorites	×	Vehicle serviced - Inspection performed - Tire checked - Maintenance inspection completed - Oil and filter changed - Wheel bearing(s)/hub(s) replaced - Noise checked - Drive belt(s) replaced - Heat shield secured - Safety inspection performed - Emissions or safety inspection performed
C	08/21/2020	97,612	New York Inspection Station		Passed safety inspection - Passed emissions inspection
C	07/23/2021		New York Motor Vehicle Dept. Amsterdam, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
C	08/16/2021	104,039	New York Inspection Station		Passed safety inspection - Passed emissions inspection
С	08/26/2021	104,308	Walmart Auto Care Center Amsterdam, NY 518-843-6899 https://www.walmart.co m 4.7 / 5.0 22 Verified Reviews	×	Vehicle serviced - Oil and filter changed - Tires rotated
С	09/23/2021	104,779	Capitaland Motors Inc. Schenectady, NY 518-399-9999 capitaland.net ★ 4.7 / 5.0 636 Verified Reviews Customer Favorites	*	Vehicle serviced
1	12/16/2021	105,115	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 136 Verified Reviews ■ 14 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Air filter checked - Air filter replaced - Headlight(s) replaced - Brakes checked
C	02/16/2022	105,171	Van Bortel Subaru Of Rochester	×	Vehicle serviced - Pre-delivery inspection completed

Rochester, NY - Front brake rotor(s) replaced - Front brake pads replaced 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ **4.8 / 5.0** 136 Verified Reviews **14** Customer Favorites 03/02/2022 New York **Passed safety inspection** Inspection Station - Passed emissions inspection Van Bortel Subaru Of Vehicle sold 03/04/2022 105,176 Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ **4.8 / 5.0** 136 Verified Reviews **14** Customer Favorites New York 03/04/2022 Registration issued or renewed Motor Vehicle Dept. - Titled or registered as personal vehicle Victor, NY - Passed safety inspection



Owner 2 Purchased: 2022



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle 2,550 mi/yr

	1	FOX		
Date	Mileage	Source		Comments
03/28/2022		New York Motor Vehicle Dept. Victor, NY		Title issued or updated - New owner reported - Loan or lien reported
06/24/2022	105,978	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 136 Verified Reviews ■ 14 Customer Favorites	×	Vehicle serviced - Remote(s) programmed
03/01/2023	107,554	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste	×	Vehicle serviced - Maintenance inspection completed - Fog light bulb(s) replaced - Oil and filter changed - Emissions or safety inspection

performed

rsoa.dealer.subaru.com/

		★ 4.8 / 5.0136 Verified Reviews■ 14 Customer Favorites		
03/01/2023		New York Inspection Station		Passed safety inspection - Passed emissions inspection
06/18/2023		New York Motor Vehicle Dept. Victor, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
11/07/2023	109,444	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 136 Verified Reviews 14 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Four wheel alignment performed
01/19/2024	109,989	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 136 Verified Reviews 14 Customer Favorites	*	Vehicle serviced - No-start/hard start condition checked - Shifter cable replaced

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

CARFAX Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:







CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved. 2/28/24 12:47:08 PM (CST)

	Vehicle History Report for this 201 on information supplied to CARE	