

This report provided free of charge by:

Van Bortel Ford

71 Marsh Rd East Rochester, NY 14445

585-460-1438

5X TOP-RATED DEALER



Customer Favorites



Vehicle History Report™

US \$44.99

2014 SUBARU XV CROSSTREK 2.0I LIMITED

VIN: JF2GPAKC4E8282368 4 DOOR WAGON/SPORT UTILITY 2.0L H4 F DOHC 16V GASOLINE ALL WHEEL DRIVE

This CARFAX Report Provided by:

Van Bortel Ford



9,801 Customer Favorites









18 Service history records



CARFAX 1-Owner vehicle



Personal vehicle



163,317 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/12/24 at 2:05:51 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History The number of owners is estimated	Owner 1
Year purchased	2014
Type of owner	Personal
Estimated length of ownership	9 yrs. 8 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	16,949/yr
Last reported odometer reading	163,317

CARFAX Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms | View Certificate

CARFAX Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated
Accident / Damage Damage reported: 01/11/2017.	Minor Damage
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

CARFAX Detailed History

Owner 1 Purchase	ed: 2014		Personal Vehicle 16,949 mi/yr
Date	Mileage	Source	Comments
05/14/2014		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 7 Customer Favorites	Vehicle offered for sale

05/16/2014	6	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 7 Customer Favorites	×	Vehicle serviced - Pre-delivery inspection completed - Emissions or safety inspection performed
05/20/2014	8	New York Inspection Station		Passed safety inspection - Emissions inspection performed
05/21/2014		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 7 Customer Favorites		Vehicle sold
06/20/2014		New York Motor Vehicle Dept. Honeoye Falls, NY		Title issued or updated - Registration issued or renewed - First owner reported - Titled or registered as personal vehicle - Passed safety inspection
08/07/2015	23,159	New York Inspection Station		Passed safety inspection - Emissions inspection performed
09/19/2015		New York Motor Vehicle Dept. Honeoye Falls, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
09/07/2016	46,175	New York Inspection Station		Passed safety inspection - Passed emissions inspection
01/11/2017		Damage Report	•	Damage reported: minor damage - Damage to undercarriage - Damage to rear - Damage to left rear
				Damage Severity Scale
			МІ	NOR MODERATE SEVERE
				Damage Location FRONT
				LEFT RIGHT







Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

		10%		
09/22/2017		New York Motor Vehicle Dept. Honeoye Falls, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
09/23/2017	69,267	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 7 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Safety inspection performed - Air filter replaced - Oil and filter changed - Tire condition and pressure checked - Cabin air filter replaced/cleaned - Emissions inspection performed
09/23/2017	69,269	New York Inspection Station		Passed safety inspection - Passed emissions inspection
04/03/2018	79,543	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 7 Customer Favorites	×	Vehicle serviced - Oil and filter changed
08/06/2018	86,826	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com	×	Vehicle serviced - Maintenance inspection completed - Four wheel alignment performed - Air filter checked

		7 Customer Favorites		 Oil and filter changed Air filter replaced Tire condition and pressure checked Wipers/washers checked Outside mirror replaced/repaired Cabin air filter replaced/cleaned
09/10/2018	88,694	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 7 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Safety inspection performed - Emissions inspection performed
09/10/2018		New York Inspection Station		Passed safety inspection - Passed emissions inspection
02/27/2019	96,360	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Oil and filter changed
08/25/2019		New York Motor Vehicle Dept. Honeoye Falls, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
08/31/2019	104,564	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	*	Vehicle serviced - Oil and filter changed - Brakes checked - Emissions or safety inspection performed
08/31/2019	104,566	New York Inspection Station		Passed safety inspection - Passed emissions inspection
02/03/2020	111,760	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Air filter replaced - Oil and filter changed - Lower ball joint(s) replaced - Cabin air filter replaced/cleaned
09/04/2020	119,121	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste	*	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Four wheel alignment performed - Front brake rotor(s) replaced - Front brake pads replaced

				- Four tires mounted
09/04/2020		New York Inspection Station		Passed safety inspection - Passed emissions inspection
01/30/2021	125,188	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	*	Vehicle serviced - Inspection performed - Tire checked - Oil and filter changed
04/26/2021	128,939	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Air filter replaced - Four wheel alignment performed - PCV valve replaced - Inner tie rod(s) replaced - Alignment performed - Oil and filter changed
07/30/2021	131,962	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Brake fluid flushed/changed
09/16/2021		New York Motor Vehicle Dept. Honeoye Falls, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
11/09/2021	135,016	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Cabin air filter replaced/cleaned - Emissions or safety inspection performed
11/09/2021	135,017	New York Inspection Station		Passed safety inspection - Passed emissions inspection
02/10/2022	138,160	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	*	Vehicle serviced - Alignment performed

08/04/2022	145,195	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Air filter replaced - Oil and filter changed
12/20/2022	151,054	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	*	Vehicle serviced - Front wiper blades/refills replaced - Oil and filter changed
12/20/2022	151,055	New York Inspection Station		Passed safety inspection - Passed emissions inspection
07/08/2023	157,843	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Tires rotated - Oil and filter changed
08/25/2023		New York Motor Vehicle Dept. Honeoye Falls, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
01/06/2024	163,317	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ 14 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Brakes checked - Ball joint(s) replaced - Safety inspection performed - Oil and filter changed - Emissions inspection performed - Emissions or safety inspection performed
01/06/2024		New York Inspection Station		Passed safety inspection - Passed emissions inspection

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

CARFAX Glossary

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX.

As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

• This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/12/24 at 2:05:51 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



@CARFAXinc



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved. 3/12/24 2:05:51 PM (CDT)

ROSSTREK vehicle (VIN: JF2) vailable as of 3/12/24 at 3:0!	GPAKC4E8282368),	Vehicle History Report for this 201 which is based on information supports.	olied to CARFAX and