




## CARFAX® Vehicle History Report™

An independent company established in 1986

US \$39.99

<p><b>Vehicle Information:</b>  <b>2011 SUBARU OUTBACK 2.5I LIMITED</b>                  VIN: 4S4BRBLC8B3372876                  4 DOOR WAGON/SPORT UTILITY                  2.5L H4 F DOHC 16V                  GASOLINE                  ALL WHEEL DRIVE  <a href="#">Standard Equipment</a>   <a href="#">Safety Options</a></p> <p><b>This CARFAX Report Provided by:</b>                  Van Bortel Ford                  71 Marsh Rd                  East Rochester, NY 14445                  833-205-1341                  www.vanbortelford.com</p> <p><b>4.9</b> ★★★★★                  74 Verified Reviews </p>	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center; width: 40px;"></td> <td>No accidents reported to CARFAX</td> </tr> <tr> <td style="text-align: center;"></td> <td>No damage reported to CARFAX</td> </tr> <tr> <td style="text-align: center;"></td> <td>CARFAX 1-Owner vehicle</td> </tr> <tr> <td style="text-align: center;"></td> <td><b>32</b> Service history records</td> </tr> <tr> <td style="text-align: center;"></td> <td>Personal vehicle</td> </tr> <tr> <td style="text-align: center;"></td> <td><b>166,958</b> Last reported odometer reading</td> </tr> </table>		No accidents reported to CARFAX		No damage reported to CARFAX		CARFAX 1-Owner vehicle		<b>32</b> Service history records		Personal vehicle		<b>166,958</b> Last reported odometer reading
	No accidents reported to CARFAX												
	No damage reported to CARFAX												
	CARFAX 1-Owner vehicle												
	<b>32</b> Service history records												
	Personal vehicle												
	<b>166,958</b> Last reported odometer reading												



This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 8/2/19 at 12:29:23 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

<div style="display: flex; align-items: center;"> <h3 style="margin: 0;">Ownership History</h3> </div> <p style="font-size: x-small; margin-top: 5px;">The number of owners is estimated</p>	<b>Owner 1</b>
Year purchased	2011
Type of owner	Personal
Estimated length of ownership	8 yrs. 3 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	20,605/yr
Last reported odometer reading	166,958

<div style="display: flex; align-items: center;"> <h3 style="margin: 0;">Title History</h3> </div> <p style="font-size: x-small; margin-top: 5px;">CARFAX guarantees the information in this section</p>	<b>Owner 1</b>
<a href="#">Salvage</a>   <a href="#">Junk</a>   <a href="#">Rebuilt</a>   <a href="#">Fire</a>   <a href="#">Flood</a>   <a href="#">Hail</a>   <a href="#">Lemon</a>	<span style="color: green; font-weight: bold;">Guaranteed</span> No Problem
<a href="#">Not Actual Mileage</a>   <a href="#">Exceeds Mechanical Limits</a>	<span style="color: green; font-weight: bold;">Guaranteed</span> No Problem
<div style="display: flex; align-items: center;"> <p style="font-size: x-small; margin: 0;"> <b style="color: green;">GUARANTEED</b> - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. <a href="#">Register</a>   <a href="#">View Terms</a>   <a href="#">View Certificate</a> </p> </div>	

<div style="display: flex; align-items: center;"> <h3 style="margin: 0;">Additional History</h3> </div> <p style="font-size: x-small; margin-top: 5px;">Not all accidents / issues are reported to CARFAX</p>	<b>Owner 1</b>
<b>Total Loss</b> No total loss reported to CARFAX.	<b>No Issues Reported</b>

<b>Structural Damage</b> No structural damage reported to CARFAX.	No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	No Issues Reported
<b>Manufacturer Recall</b> Check with an authorized Subaru dealer for any open recalls.	No Recalls Reported
<b>Basic Warranty</b> <a href="#">Original warranty</a> estimated to have expired.	<b>Warranty Expired</b>



## Detailed History

Glossary

<b>Owner 1</b>	Date:	Mileage:	Source:	Comments:
Purchased: 2011 Type: Personal Where: New York Est. miles/year: 20,605/yr Est. length owned: 4/1/11 - 7/30/19 (8 yrs. 3 mo.)	01/03/2011		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7  67 Verified Reviews	Vehicle offered for sale
	01/28/2011	11	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7  67 Verified Reviews	Pre-delivery inspection completed Mirror(s) checked
	03/28/2011	109	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7  67 Verified Reviews	Safety inspection performed
	04/01/2011		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7  67 Verified Reviews	Vehicle sold
	04/01/2011		New York Inspection Station	Emissions inspection performed Passed safety inspection <a href="#">View what was inspected</a>
	04/01/2011		New York Motor Vehicle Dept. Rochester, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection
	05/10/2011		New York Motor Vehicle Dept. Rochester, NY	Title issued or updated First owner reported Loan or lien reported

06/21/2011	4,290	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Oil and filter changed
09/28/2011	8,478	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	7,500 mile service performed
01/11/2012	12,164	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Oil and filter changed
04/11/2012	15,037	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Vehicle serviced
04/11/2012		New York Inspection Station	Passed safety inspection Emissions inspection performed  <a href="#">View what was inspected</a>
05/24/2012	17,413	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	One tire balanced
08/29/2012	23,548	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	7,500 mile service performed Oil and filter changed Tire condition and pressure checked
12/20/2012	28,526	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Oil and filter changed
03/11/2013	32,610	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	30,000 mile service performed Wipers/washers checked Oil and filter changed Tires rotated Rear wiper blade replaced Safety inspection performed Headlight bulb(s) replaced
03/11/2013		New York Inspection Station	Passed safety inspection Passed emissions inspection  <a href="#">View what was inspected</a>
05/21/2013		New York Motor Vehicle Dept. Rochester, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection

07/08/2013	38,566	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Maintenance inspection completed 7,500 mile service performed Oil and filter changed
11/05/2013	42,669	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Oil and filter changed
03/06/2014	48,155	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	15,000 mile service performed Safety inspection performed Tire condition and pressure checked Emissions inspection performed
03/06/2014		New York Inspection Station	Passed safety inspection Emissions inspection performed  <a href="#">View what was inspected</a>
06/28/2014	53,635	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Four wheel alignment performed Oil and filter changed Tire condition and pressure checked Four tires mounted
01/21/2015	63,159	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	60,000 mile service performed Rear brake pads replaced Rear brake rotor(s) replaced Brake rotor(s) replaced Oil and filter changed Tires rotated
02/23/2015	64,915	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Vehicle serviced
03/06/2015	65,399	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Safety inspection performed Emissions inspection performed
03/06/2015		New York Inspection Station	Passed safety inspection Passed emissions inspection  <a href="#">View what was inspected</a>
05/28/2015		New York Motor Vehicle Dept. Rochester, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection
12/14/2015	77,408	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Recommended maintenance performed Oil and filter changed

01/06/2016	77,759	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Vehicle serviced
03/21/2016	82,376	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Tire condition and pressure checked Oil and filter changed Front turn signal/parking bulb(s) replaced Safety inspection performed
03/21/2016		New York Inspection Station	Passed safety inspection Passed emissions inspection  <a href="#">View what was inspected</a>
05/25/2016	86,561	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Tire condition and pressure checked
08/31/2016	91,331	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Air filter replaced
12/09/2016	99,281	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Front brakes serviced Cabin air filter replaced/cleaned Front brake rotor(s) replaced Front brake pads replaced Brake rotor(s) replaced Oil and filter changed Tire condition and pressure checked
04/10/2017	107,842	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Safety inspection performed Oil and filter changed Emissions inspection performed
04/10/2017		New York Inspection Station	Passed safety inspection Passed emissions inspection  <a href="#">View what was inspected</a>
07/06/2017		New York Motor Vehicle Dept. Fairport, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection Registration updated when owner moved the vehicle to a new location
09/21/2017	119,756	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Maintenance inspection completed Engine/powertrain computer/module checked Tire condition and pressure checked Battery replaced Rear brake pads replaced Rear brake rotor(s) replaced Brake rotor(s) replaced Battery/charging system checked Air filter replaced

01/05/2018	126,605	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Maintenance inspection completed Oil and filter changed
03/23/2018	134,514	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Oil and filter changed
04/30/2018	136,993	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Maintenance inspection completed
04/30/2018		New York Inspection Station	Passed safety inspection Passed emissions inspection  <a href="#">View what was inspected</a>
07/26/2018	145,408	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Maintenance inspection completed Oil and filter changed
12/17/2018	156,072	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Oil and filter changed Light bulb(s) replaced Headlight bulb(s) replaced
02/15/2019	160,492	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Maintenance inspection completed Four wheel alignment performed Oil and filter changed
04/30/2019	166,598	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Maintenance inspection completed Oil and filter changed Emissions or safety inspection performed
04/30/2019	166,958	New York Inspection Station	Passed safety inspection Passed emissions inspection  <a href="#">View what was inspected</a>
07/03/2019		New York Motor Vehicle Dept. Fairport, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection
07/30/2019		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 67 Verified Reviews	Vehicle offered for sale

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



## Glossary

[View Full Glossary](#)

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

### Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: [facebook.com/CARFAX](https://www.facebook.com/CARFAX) [@CarfaxReports](https://twitter.com/CarfaxReports)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2019 CARFAX, Inc., a unit of IHS Markit. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

8/2/19 12:29:23 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2011 SUBARU OUTBACK vehicle (VIN: 4S4BRBLC8B3372876), which is based on information supplied to CARFAX and available as of 8/2/19 at 1:29 PM (EDT).

\_\_\_\_\_  
Customer Signature

\_\_\_\_\_  
Date

\_\_\_\_\_  
Dealer Signature

\_\_\_\_\_  
Date