



CARFAX[®] Vehicle History Report[™]

An independent company established in 1986

US \$39.99

Vehicle Information:
2006 HONDA ODYSSEY EXL
 VIN:5FNRL38606B435801
 VAN
 3.5L V6 F SOHC 24V
 GASOLINE
 FRONT WHEEL DRIVE
[Standard Equipment](#) | [Safety Options](#)


This CARFAX Report Provided by:
 Van Bortel Ford
 71 Marsh Rd
 East Rochester, NY 14445
 833-205-1341
 www.vanbortelford.com

4.7 ★★★★★
 22 Verified Reviews



| | |
|---|---|
|  | No accidents reported to CARFAX |
|  | No damage reported to CARFAX |
|  | CARFAX 1-Owner vehicle |
|  | 10 Service history records |
|  | Personal vehicle |
|  | 182,058 Last reported odometer reading |






This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/4/19 at 12:15:34 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

|  Ownership History | Owner 1 |
|--|-----------|
| The number of owners is estimated | |
| Year purchased | 2006 |
| Type of owner | Personal |
| Estimated length of ownership | 13 years |
| Owned in the following states/provinces | New York |
| Estimated miles driven per year | 14,926/yr |
| Last reported odometer reading | 182,058 |



|  Title History | Owner 1 |
|---|---------------------------------|
| CARFAX guarantees the information in this section | |
| Salvage Junk Rebuilt Fire Flood Hail Lemon | Guaranteed No Problem |
| Not Actual Mileage Exceeds Mechanical Limits | Guaranteed No Problem |
|  <p>GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. Register View Terms View Certificate</p> | |


|  Additional History | Owner 1 |
|---|--|
| Not all accidents / issues are reported to CARFAX | |
| Total Loss No total loss reported to CARFAX. |  No Issues Reported |
| Structural Damage No structural damage reported to CARFAX. |  No Issues Reported |






| | |
|---|-------------------------|
| Airbag Deployment No airbag deployment reported to CARFAX. | No Issues Reported |
| Odometer Check No indication of an odometer rollback. | No Issues Indicated |
| Accident / Damage No accidents or damage reported to CARFAX. | No Issues Reported |
| Manufacturer Recall No open recalls reported to CARFAX. Check with an authorized Honda dealer for any open recalls. | No Recalls Reported |
| Basic Warranty Original warranty estimated to have expired. | Warranty Expired |



Detailed History

Glossary

| Owner 1 | Date: | Mileage: | Source: | Comments: |
|--|------------|----------|--|--|
| Owner 1 Purchased: 2006 Type: Personal Where: New York Est. miles/year: 14,926/yr Est. length owned: 5/15/06 - 5/30/19 (13 years) Low mileage! This owner drove less than the industry average of 15,000 miles per year.  | 05/05/2006 | 1 | Ralph Honda Rochester, NY 585-225-3200 ralphdoneright.com 4.5 13 Verified Reviews | Pre-delivery inspection completed Vehicle washed/detailed Emissions or safety inspection performed |
| | 05/15/2006 | 14 | New York Inspection Station | Emissions inspection performed Dealer had vehicle inspected to prepare it for sale Passed safety inspection View what was inspected |
| | 05/15/2006 | | New York Motor Vehicle Dept. North Chili, NY | Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection |
| | 06/16/2006 | | New York Motor Vehicle Dept. North Chili, NY | Title issued or updated First owner reported |
| | 04/27/2007 | 15,492 | New York Inspection Station | Emissions inspection performed Passed safety inspection View what was inspected |
| | 07/04/2007 | | New York Motor Vehicle Dept. North Chili, NY | Title issued or updated Registration issued or renewed Titled or registered as personal vehicle Loan or lien reported Passed safety inspection |
| | 04/29/2009 | 43,626 | New York Inspection Station | Passed safety inspection Passed emissions inspection View what was inspected |
| | 07/12/2009 | | New York Motor Vehicle Dept. North Chili, NY | Title issued or updated Registration issued or renewed Titled or registered as personal vehicle Loan or lien reported Passed safety inspection |

| | | | |
|------------|--------|--|--|
| 07/13/2009 | 49,036 | Ralph Honda Rochester, NY 585-225-3200 ralphdoneright.com 4.5  13 Verified Reviews | Recommended maintenance performed 30,000 mile service performed Four wheel alignment performed Cabin air filter checked Power steering fluid flushed/changed Four tires mounted Brakes checked Oil and filter changed Tire condition and pressure checked Alignment performed Cabin air filter replaced/cleaned Steering/suspension checked Four tires balanced Vehicle washed/detailed |
| 12/22/2009 | 54,889 | Valvoline Instant Oil Change Rochester, NY 585-889-1540 vioc.com 4.4  42 Verified Reviews | Oil and filter changed |
| 05/01/2010 | 60,006 | Valvoline Instant Oil Change Rochester, NY 585-889-1540 vioc.com 4.4  42 Verified Reviews | Emissions inspection performed |
| 05/01/2010 | | New York Inspection Station | Passed safety inspection Passed emissions inspection View what was inspected |
| 05/19/2010 | 60,649 | Valvoline Instant Oil Change Rochester, NY 585-889-1540 vioc.com 4.4  42 Verified Reviews | Oil and filter changed |
| 05/06/2011 | | Ralph Honda Rochester, NY 585-225-3200 ralphdoneright.com 4.5  13 Verified Reviews | Oil and filter changed Tire condition and pressure checked Cabin air filter checked Alignment performed Four tires mounted Vehicle washed/detailed Cabin air filter replaced/cleaned Four wheel alignment performed Four tires balanced Safety inspection performed Emissions inspection performed |
| 05/06/2011 | 73,089 | New York Inspection Station | Passed safety inspection Passed emissions inspection View what was inspected |
| 08/05/2011 | | New York Motor Vehicle Dept. North Chili, NY | Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection |

| | | | |
|------------|---------|---|--|
| 10/24/2011 | 79,357 | Valvoline Instant Oil Change Rochester, NY 585-889-1540 vioc.com 4.4  42 Verified Reviews | Oil and filter changed |
| 03/27/2012 | 84,342 | Ralph Honda Rochester, NY 585-225-3200 ralphdoneright.com 4.5  13 Verified Reviews | Recommended maintenance performed 30,000 mile service performed Vehicle washed/detailed Power steering pump replaced Interior trim checked Exhaust system checked Wiper(s) replaced Front brake rotor(s) replaced Rear brake pads replaced Battery replaced |
| 05/31/2012 | 87,744 | New York Inspection Station | Passed safety inspection Passed emissions inspection View what was inspected |
| 05/06/2013 | 102,859 | New York Inspection Station | Passed safety inspection Passed emissions inspection View what was inspected |
| 07/09/2013 | | New York Motor Vehicle Dept. North Chili, NY | Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection |
| 06/02/2014 | 120,715 | New York Inspection Station | Passed safety inspection Emissions inspection performed View what was inspected |
| 03/19/2015 | 132,595 | Valvoline Instant Oil Change Gates, NY 585-247-4940 vioc.com 4.4  46 Verified Reviews | Oil and filter changed Cabin air filter replaced/cleaned |
| 06/26/2015 | 138,955 | New York Inspection Station | Passed safety inspection Passed emissions inspection View what was inspected |
| 07/06/2015 | | New York Motor Vehicle Dept. North Chili, NY | Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection |
| 02/08/2016 | 148,551 | Ralph Honda Rochester, NY 585-225-3200 ralphdoneright.com 4.5  13 Verified Reviews | Emission system checked |
| 07/12/2016 | 154,114 | New York Inspection Station | Passed safety inspection Passed emissions inspection View what was inspected |
| 06/02/2017 | | New York Motor Vehicle Dept. North Chili, NY | Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection |

| | | | |
|------------|---------|--|--|
| 08/10/2017 | 173,293 | New York Inspection Station | Passed safety inspection Passed emissions inspection View what was inspected |
| 07/23/2018 | 182,058 | New York Inspection Station | Passed safety inspection Passed emissions inspection View what was inspected |
| 05/30/2019 | | Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubaruroche stersoa.dealer.subar u.com/ | Vehicle offered for sale |

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

[View Full Glossary](#)

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: [facebook.com/CARFAX](https://www.facebook.com/CARFAX) [@CarfaxReports](https://twitter.com/CarfaxReports)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2019 CARFAX, Inc., a unit of IHS Markit. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

6/4/19 12:15:34 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2006 HONDA ODYSSEY vehicle (VIN: 5FNRL38606B435801), which is based on information supplied to CARFAX and available as of 6/4/19 at 1:15 PM (EDT).

Customer Signature

Date

Dealer Signature

Date