














Display CARFAX in online listings:


	This report provided free of charge by: <b>Van Bortel Ford</b> 71 Marsh Rd East Rochester, NY 14445 585-460-1438	<b>5X TOP-RATED DEALER</b> <b>★ 4.8 / 5.0</b> 1,485 Verified Reviews	<b>♥ 10,209</b> Customer Favorites
---	--	--	---------------------------------------

	<b>Vehicle History Report™</b>	US \$44.99
<b>2013 SUBARU OUTBACK 2.5I PREMIUM</b> VIN: 4S4BRBGC2D3200047 4 DOOR WAGON/SPORT UTILITY 2.5L H4 F DOHC 16V GASOLINE ALL WHEEL DRIVE This CARFAX Report Provided by: <b>Van Bortel Ford</b> ★ 4.8 / 5.0 1,485 Verified Reviews ♥ 10,209 Customer Favorites	 No accidents or damage reported to CARFAX	
	 <b>50</b> Service history records	
	 CARFAX 1-Owner vehicle	
	 Personal vehicle	
	 Last owned in New York	
	 <b>177,439</b> Last reported odometer reading	



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/24/24 at 7:33:57 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	<b>Owner 1</b>
<b>Total Loss</b> No total loss reported to CARFAX.	 No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	 No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	 No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	 No Issues Indicated


<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	<b>Warranty Expired</b>









<b>CARFAX Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	


<b>CARFAX Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2012
Type of owner	Personal
Estimated length of ownership	11 yrs. 10 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	15,534/yr
Last reported odometer reading	177,439
















<b>CARFAX Detailed History</b>			
 <b>Owner 1</b> Purchased: 2012	Personal Vehicle 15,534 mi/yr		
Date	Mileage	Source	Comments
07/20/2012		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  <b>4.9 / 5.0</b>	<b>Vehicle offered for sale</b>






167 Verified Reviews

 7 Customer Favorites

07/26/2012	13	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews  7 Customer Favorites	 <b>Vehicle serviced</b> - Pre-delivery inspection completed - Safety inspection performed - Emissions or safety inspection performed
07/26/2012		New York Inspection Station	<b>Passed safety inspection</b> - Emissions inspection performed
07/30/2012		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews  7 Customer Favorites	<b>Vehicle sold</b>
08/24/2012		New York Motor Vehicle Dept. Waterloo, NY	<b>Title issued or updated</b> - Registration issued or renewed - First owner reported - Titled or registered as personal vehicle - Loan or lien reported - Passed safety inspection
11/06/2012	3,620	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews  7 Customer Favorites	 <b>Vehicle serviced</b>
03/01/2013	7,474	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews  7 Customer Favorites	 <b>Vehicle serviced</b> - Oil and filter changed
05/15/2013	9,700	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews	 <b>Vehicle serviced</b> - Steering column replaced

 7 Customer Favorites

07/29/2013	12,536	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.9 / 5.0 167 Verified Reviews  7 Customer Favorites	 <b>Vehicle serviced</b> - Safety inspection performed - Emissions or safety inspection performed
07/29/2013		New York Inspection Station	<b>Passed safety inspection</b> - Emissions inspection performed
08/28/2013		New York Motor Vehicle Dept. Waterloo, NY	<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection
11/05/2013	16,235	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.9 / 5.0 167 Verified Reviews  7 Customer Favorites	 <b>Vehicle serviced</b> - Oil and filter changed
05/19/2014	23,615	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.9 / 5.0 167 Verified Reviews  7 Customer Favorites	 <b>Vehicle serviced</b> - Oil and filter changed
08/02/2014	27,222	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.9 / 5.0 167 Verified Reviews  7 Customer Favorites	 <b>Vehicle serviced</b> - Safety inspection performed - Emissions or safety inspection performed
08/02/2014		New York Inspection Station	<b>Passed safety inspection</b> - Passed emissions inspection
10/30/2014	31,659	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.9 / 5.0 167 Verified Reviews  7 Customer Favorites	 <b>Vehicle serviced</b> - 30,000 mile service performed - Oil and filter changed - Tires rotated

03/16/2015	38,445	Fox Toyota Subaru Auburn, NY 315-253-7341 foxtoyotasubaru.com ★ 4.6 / 5.0 151 Verified Reviews	 <b>Vehicle serviced</b> - Headlight bulb(s) replaced
05/01/2015	41,208	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ❤️ 7 Customer Favorites	 <b>Vehicle serviced</b> - Tire condition and pressure checked - Oil and filter changed
09/01/2015	47,419	New York Inspection Station	<b>Passed safety inspection</b> - Passed emissions inspection
09/03/2015		New York Motor Vehicle Dept. Waterloo, NY	<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection - Registration updated when owner moved the vehicle to a new location
09/29/2015	48,069	Inspection Co.	<b>Inspection performed</b>
12/04/2015	51,986	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ❤️ 7 Customer Favorites	 <b>Vehicle serviced</b> - Tire(s) balanced - Tire(s) mounted - Four wheel alignment performed - Four tires balanced - Four tires mounted - Four tires replaced - Rear brake pads replaced - Rear brake rotor(s) replaced - Tire condition and pressure checked - Oil and filter changed - Back-up camera replaced
08/23/2016	63,602	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ❤️ 7 Customer Favorites	 <b>Vehicle serviced</b> - 60,000 mile service performed - Safety inspection performed - Air filter replaced - Oil and filter changed - Emissions inspection performed - Emissions or safety inspection performed
08/23/2016		New York Inspection Station	<b>Passed safety inspection</b> - Passed emissions inspection
12/08/2016	67,878	Van Bortel Subaru Victor, NY 585-924-5230	 <b>Vehicle serviced</b> - Maintenance inspection completed - Oil and filter changed

vanbortelsubaru.com

★ 4.9 / 5.0

167 Verified Reviews

♥ 7 Customer Favorites

- Tire condition and pressure checked  
- Wipers/washers checked

05/24/2017 72,890

Valvoline Instant Oil  
Change  
Geneva, NY  
315-789-1373  
vioc.com

★ 4.8 / 5.0

87 Verified Reviews

♥ 81 Customer Favorites



**Vehicle serviced**

- Oil and filter changed

05/31/2017 73,210

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.9 / 5.0

167 Verified Reviews

♥ 7 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed  
- Oil and filter changed  
- Tire condition and pressure checked  
- Wipers/washers checked  
- Trailer hitch installed  
- Four tires balanced  
- Tires rotated

08/15/2017 77,528

Valvoline Instant Oil  
Change  
Geneva, NY  
315-789-1373  
vioc.com

★ 4.8 / 5.0

87 Verified Reviews

♥ 81 Customer Favorites



**Vehicle serviced**

- Oil and filter changed

09/12/2017 80,615

Valvoline Instant Oil  
Change  
Geneva, NY  
315-789-1373  
vioc.com

★ 4.8 / 5.0

87 Verified Reviews

♥ 81 Customer Favorites



**Vehicle serviced**

- Emissions inspection performed

09/12/2017

New York  
Inspection Station

**Passed safety inspection**

- Passed emissions inspection

09/12/2017

New York  
Motor Vehicle Dept.  
Waterloo, NY

**Registration issued or renewed**

- Titled or registered as personal vehicle  
- Passed safety inspection

10/09/2017 82,595

Valvoline Instant Oil  
Change  
Geneva, NY  
315-789-1373  
vioc.com



**Vehicle serviced**

- Fluids checked

★ 4.8 / 5.0  
87 Verified Reviews  
♥ 81 Customer Favorites

10/31/2017 83,858

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- License plate light bulb(s) replaced
- Oil and filter changed
- Battery replaced
- Light bulb(s) replaced
- Tire condition and pressure checked
- Engine/powertrain computer/module reprogrammed
- Four tires balanced
- Tires rotated

02/19/2018 90,831

Valvoline Instant Oil  
Change  
Geneva, NY  
315-789-1373  
vioc.com

★ 4.8 / 5.0  
87 Verified Reviews  
♥ 81 Customer Favorites



**Vehicle serviced**

- Oil and filter changed
- High mount brake light bulb replaced
- Exterior light bulb(s) replaced
- Cabin air filter replaced/cleaned

05/25/2018 96,301

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites



**Vehicle serviced**

- 30,000 mile service performed
- Battery/charging system checked
- Air filter replaced
- Oil and filter changed

08/31/2018 102,215

Valvoline Instant Oil  
Change  
Geneva, NY  
315-789-1373  
vioc.com

★ 4.8 / 5.0  
87 Verified Reviews  
♥ 81 Customer Favorites



**Vehicle serviced**

- Oil and filter changed

09/28/2018 103,593

Valvoline Instant Oil  
Change  
Geneva, NY  
315-789-1373  
vioc.com

★ 4.8 / 5.0  
87 Verified Reviews  
♥ 81 Customer Favorites









**Vehicle serviced**

- Emissions inspection performed






09/28/2018







New York

**Passed safety inspection**

		Inspection Station	- Passed emissions inspection
10/15/2018	104,649	<p>Midas Geneva, NY 315-789-0156 midas.com</p> <p>★ 4.8 / 5.0 41 Verified Reviews ♥ 23 Customer Favorites</p>	<p> <b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Four wheel alignment performed</li> <li>- Alignment performed</li> <li>- Four tires balanced</li> <li>- Four tires mounted</li> </ul>
01/19/2019	108,975	<p>Valvoline Instant Oil Change Geneva, NY 315-789-1373 vioc.com</p> <p>★ 4.8 / 5.0 87 Verified Reviews ♥ 81 Customer Favorites</p>	<p> <b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Oil and filter changed</li> <li>- High mount brake light bulb replaced</li> <li>- Exterior light bulb(s) replaced</li> <li>- Headlight bulb(s) replaced</li> <li>- Fog light bulb(s) replaced</li> </ul>
04/23/2019	114,000	<p>Valvoline Instant Oil Change Geneva, NY 315-789-1373 vioc.com</p> <p>★ 4.8 / 5.0 87 Verified Reviews ♥ 81 Customer Favorites</p>	<p> <b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Fluids checked</li> </ul>
05/28/2019	114,410	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.9 / 5.0 167 Verified Reviews ♥ 7 Customer Favorites</p>	<p> <b>Vehicle serviced</b></p>
06/06/2019		<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.9 / 5.0 167 Verified Reviews ♥ 7 Customer Favorites</p>	<p> <b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Drive belt(s) replaced</li> </ul>
06/18/2019	115,011	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.9 / 5.0 167 Verified Reviews ♥ 7 Customer Favorites</p>	<p> <b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Tire(s) balanced</li> </ul>



07/12/2019	116,252	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ❤️ 7 Customer Favorites	 <b>Vehicle serviced</b> - Four wheel alignment performed - Engine serviced
09/03/2019	119,399	New York Inspection Station	<b>Passed safety inspection</b> - Passed emissions inspection
09/03/2019		New York Motor Vehicle Dept. Waterloo, NY	<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection
01/24/2020	125,736	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ❤️ 7 Customer Favorites	 <b>Vehicle serviced</b> - Front wiper blades/refills replaced
07/03/2020	130,196	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ❤️ 7 Customer Favorites	 <b>Vehicle serviced</b> - Maintenance inspection completed - Engine oil/fluid leak checked - Rear brakes replaced
08/10/2020	131,539	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ❤️ 7 Customer Favorites	 <b>Vehicle serviced</b> - Two tires balanced - Tires rotated - Oil and filter changed - Light bulb(s) replaced - Tire pressure monitoring system reset
08/13/2020		Farmington Service Shortsville, NY 585-924-3470 farmingtonservice.com/ ★ 5.0 / 5.0 21 Verified Reviews ❤️ 1 Customer Favorite	 <b>Vehicle serviced</b>
11/20/2020	133,000	New York Inspection Station	<b>Passed safety inspection</b> - Passed emissions inspection

01/02/2021	133,768	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ❤️ 7 Customer Favorites		<b>Vehicle serviced</b> - Maintenance inspection completed - Valve body replaced
03/19/2021	135,491	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ❤️ 7 Customer Favorites		<b>Vehicle serviced</b>
07/24/2021	138,818	Monro Auto Service & Tire Centers Waterloo, NY 315-539-2668 monro.com ★ 4.4 / 5.0 18 Verified Reviews		<b>Vehicle serviced</b> - Maintenance inspection completed - Recommended maintenance performed - Tire(s) replaced - Tire(s) mounted
09/07/2021		New York Motor Vehicle Dept. Waterloo, NY		<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection
12/08/2021	145,061	New York Inspection Station		<b>Passed safety inspection</b> - Passed emissions inspection
02/27/2022	148,674	Monro Auto Service & Tire Centers Waterloo, NY 315-539-2668 monro.com ★ 4.4 / 5.0 18 Verified Reviews		<b>Vehicle serviced</b> - Maintenance inspection completed - Recommended maintenance performed
05/19/2022	151,598	Monro Auto Service & Tire Centers Waterloo, NY 315-539-2668 monro.com ★ 4.4 / 5.0 18 Verified Reviews		<b>Vehicle serviced</b> - Maintenance inspection completed - Recommended maintenance performed - Tires rotated - Brakes checked - A/C refrigerant recharged - A/C system serviced - Battery/charging system checked - Oil and filter changed - Brakes serviced
05/26/2022	151,945	Van Bortel Subaru Victor, NY		<b>Vehicle serviced</b> - Maintenance inspection completed

585-924-5230  
vanbortelsubaru.com  
★ 4.9 / 5.0  
167 Verified Reviews  
❤️ 7 Customer Favorites

- Differential fluid flushed/changed
- Brake fluid flushed/changed
- Air filter replaced
- Light bulb(s) replaced
- Fog light bulb(s) replaced
- Rear brake pads replaced
- Antifreeze/coolant flushed/changed

06/22/2022 152,800  
Monro Auto Service &  
Tire Centers  
Waterloo, NY  
315-539-2668  
monro.com  
★ 4.4 / 5.0  
18 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Recommended maintenance performed

12/06/2022 161,192  
Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.9 / 5.0  
167 Verified Reviews  
❤️ 7 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Rear brakes replaced
- Two tires balanced
- Tires rotated
- Drivability/performance checked
- Rear brake pads replaced
- Rear brake rotor(s) replaced
- Oil and filter changed
- Rear wiper blade replaced
- Tire pressure monitoring system reset
- Cabin air filter replaced/cleaned
- Lights checked

12/06/2022  
New York  
Inspection Station

**Passed safety inspection**

- Passed emissions inspection

02/27/2023 165,770  
Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.9 / 5.0  
167 Verified Reviews  
❤️ 7 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Front axle(s) replaced/repared
- Muffler replaced
- Back-up camera replaced

06/17/2023  
Monro Auto Service &  
Tire Centers  
Waterloo, NY  
315-539-2668  
monro.com  
★ 4.4 / 5.0  
18 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Recommended maintenance performed


07/19/2023  
Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.9 / 5.0



**Vehicle serviced**

- Maintenance inspection completed
- Two tires balanced
- Tires rotated
- Oil and filter changed

167 Verified Reviews

 7 Customer Favorites

- Interior cleaned
- Tire pressure monitoring system reset

08/14/2023 171,493

Monro Auto Service &  
Tire Centers  
Waterloo, NY  
315-539-2668  
monro.com

 4.4 / 5.0

18 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Recommended maintenance performed

09/19/2023

Monro Auto Service &  
Tire Centers  
Waterloo, NY  
315-539-2668  
monro.com

 4.4 / 5.0

18 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Recommended maintenance performed
- Tire repaired
- Tire condition and pressure checked

09/29/2023

New York  
Motor Vehicle Dept.  
Waterloo, NY

**Registration issued or renewed**

- Titled or registered as personal vehicle
- Passed safety inspection

10/04/2023

Monro Auto Service &  
Tire Centers  
Waterloo, NY  
315-539-2668  
monro.com

 4.4 / 5.0

18 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Recommended maintenance performed
- Cabin air filter replaced/cleaned
- Emissions inspection performed

10/04/2023 173,718

New York  
Inspection Station

**Passed safety inspection**


- Passed emissions inspection

12/29/2023 177,439

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.9 / 5.0

167 Verified Reviews

 7 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Two tires balanced
- Tires rotated
- Battery/charging system checked
- Spark plug(s) replaced
- Sunroof checked
- Tire pressure monitoring system reset
- Fog light bulb(s) replaced
- Oil and filter changed
- Lights checked
- Emissions or safety inspection performed

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



Glossary

**First Owner**

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

**Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

**Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.  
6/24/24 7:33:57 AM (CDT)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2013 SUBARU OUTBACK vehicle (VIN: 4S4BRBGC2D3200047), which is based on information supplied to CARFAX and available as of 6/24/24 at 8:33 AM (EDT).**

\_\_\_\_\_  
**Customer Signature**

\_\_\_\_\_  
**Date**

\_\_\_\_\_  
**Dealer Signature**

\_\_\_\_\_  
**Date**