


Display CARFAX in online listings:




This report provided free of charge by:

**Van Bortel Ford**  
 71 Marsh Rd  
 East Rochester, NY 14445  
 585-460-1438

**5X TOP-RATED DEALER**







★ **4.8 / 5.0**  
 1,485 Verified Reviews

♥ **10,210**  
 Customer Favorites












## Vehicle History Report™



US \$44.99


<p><b>2013 SUBARU OUTBACK 2.5I LIMITED</b></p> <p>VIN: 4S4BRBPC6D3203422              4 DOOR WAGON/SPORT              UTILITY              2.5L H4 F DOHC 16V              GASOLINE              ALL WHEEL DRIVE</p> <p>This CARFAX Report Provided by:  <b>Van Bortel Ford</b>              ★ <b>4.8 / 5.0</b>              1,485 Verified Reviews              ♥ <b>10,210</b> Customer Favorites</p>	<ul style="list-style-type: none"> <li style="margin-bottom: 10px;"> <b>No accidents or damage reported to CARFAX</b></li> <li style="margin-bottom: 10px;"> <b>24</b> Service history records</li> <li style="margin-bottom: 10px;"> <b>2</b> Previous owners</li> <li style="margin-bottom: 10px;"> <b>Types of owners:</b> Personal lease, Personal</li> <li style="margin-bottom: 10px;"> <b>Last owned in New York</b></li> <li style="margin-bottom: 10px;"> <b>102,848</b> Last reported odometer reading</li> </ul>
---	--




This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/27/24 at 11:17:39 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	<b>Owner 1</b>	<b>Owner 2</b>
<p><b>Total Loss</b> No total loss reported to CARFAX.</p>	 No Issues Reported	 No Issues Reported
<p><b>Structural Damage</b> No structural damage reported to CARFAX.</p>	 No Issues Reported	 No Issues Reported
<p><b>Airbag Deployment</b> No airbag deployment reported to CARFAX.</p>	 No Issues Reported	 No Issues Reported
<p><b>Odometer Check</b> No indication of an odometer rollback.</p>	 No Issues Indicated	 No Issues Indicated

<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	<b>Warranty Expired</b>	<b>Warranty Expired</b>

 <b>Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>	<b>Owner 2</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms   View Certificate		

 <b>Ownership History</b> The number of owners is estimated	<b>Owner 1</b>	<b>Owner 2</b>
Year purchased	2012	2016
Type of owner	Personal lease	Personal
Estimated length of ownership	3 yrs. 4 mo.	8 yrs. 4 mo.
Owned in the following states/provinces	New York	New York
Estimated miles driven per year	10,104/yr	8,119/yr
Last reported odometer reading	34,446	102,848

 <b>Detailed History</b>			
 <b>Owner 1</b> Purchased: 2012		<b>Low mileage!</b> This owner drove less than the industry average of 15,000 miles per year.	Personal Lease Vehicle 10,104 mi/yr
<b>Date</b>	<b>Mileage</b>	<b>Source</b>	<b>Comments</b>
07/20/2012		Van Bortel Subaru Victor, NY 585-924-5230	<b>Vehicle offered for sale</b>

vanbortelsubaru.com

★ 4.9 / 5.0

167 Verified Reviews

♥ 7 Customer Favorites

08/07/2012 38

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.9 / 5.0

167 Verified Reviews

♥ 7 Customer Favorites



**Vehicle serviced**

- Pre-delivery inspection completed
- Safety inspection performed
- Emissions or safety inspection performed

08/07/2012 42

New York  
Inspection Station

**Passed safety inspection**

- Emissions inspection performed

08/09/2012

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.9 / 5.0

167 Verified Reviews

♥ 7 Customer Favorites

**Vehicle sold**

08/09/2012

New York  
Motor Vehicle Dept.  
Canandaigua, NY

**Registration issued or renewed**

- Titled or registered as personal lease vehicle
- Passed safety inspection

09/05/2012

New York  
Motor Vehicle Dept.  
Fort Worth, TX

**Title issued or updated**

- First owner reported

05/22/2013 5,999

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.9 / 5.0

167 Verified Reviews

♥ 7 Customer Favorites



**Vehicle serviced**

- Steering column replaced

06/28/2013 7,667

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.9 / 5.0

167 Verified Reviews

♥ 7 Customer Favorites



**Vehicle serviced**





- Oil and filter changed
- Two tires balanced
- Tires rotated

08/05/2013 8,705

New York  
Inspection Station

**Passed safety inspection**

- Emissions inspection performed

08/05/2013		New York Motor Vehicle Dept. Canandaigua, NY	<b>Registration issued or renewed</b> - Passed safety inspection
03/24/2014	15,470	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ♥ 7 Customer Favorites	 <b>Vehicle serviced</b> - Oil and filter changed
04/10/2014	16,013	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ♥ 7 Customer Favorites	 <b>Vehicle serviced</b> - Tire repaired
08/19/2014	20,178	New York Inspection Station	<b>Passed safety inspection</b> - Passed emissions inspection
08/08/2015	29,426	New York Inspection Station	<b>Passed safety inspection</b> - Passed emissions inspection
08/13/2015		New York Motor Vehicle Dept. Canandaigua, NY	<b>Registration issued or renewed</b> - Passed safety inspection
01/04/2016	34,411	Subaru Certified Dealer Victor, NY 	<b>Offered for sale as a Subaru Certified Pre-owned Vehicle</b> - Graphite Gray Metallic exterior - Black interior
01/04/2016		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ♥ 7 Customer Favorites	<b>Vehicle offered for sale</b>
01/04/2016		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews	 <b>Vehicle serviced</b> - Pre-delivery inspection completed - Recommended maintenance performed - 30,000 mile service performed - Four wheel alignment performed - Front brake rotor(s) replaced

♥ 7 Customer Favorites

- Front brake pads replaced
- Rear brake pads replaced
- Rear brake rotor(s) replaced
- Four tires mounted
- Tire condition and pressure checked
- Oil and filter changed



Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

01/29/2016 34,433 Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites



**Vehicle serviced**  
- Safety inspection performed

02/03/2016 34,446 New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

02/06/2016 Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

**Vehicle sold**

02/06/2016 New York  
Motor Vehicle Dept.  
Rochester, NY

**Registration issued or renewed**  
- Passed safety inspection

👤 **Owner 2**  
Purchased: 2016



**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle  
8,119 mi/yr

Date	Mileage	Source	Comments
02/22/2016		New York Motor Vehicle Dept. Rochester, NY	<b>Title issued or updated</b> - New owner reported - Loan or lien reported
04/02/2016		New York Motor Vehicle Dept. Rochester, NY	<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection
11/30/2016	42,143	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com	<b>Vehicle serviced</b> - Oil and filter changed - Tire condition and pressure checked

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

03/09/2017 44,314

New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

05/06/2017 45,639

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**  
- Maintenance inspection completed

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

10/21/2017 50,240

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**  
- Maintenance inspection completed  
- Air filter replaced  
- Oil and filter changed  
- Tire condition and pressure checked  
- Four tires balanced  
- Tires rotated  
- Cabin air filter replaced/cleaned

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

01/23/2018

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**  
- Maintenance inspection completed  
- Back-up camera replaced

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

04/02/2018 56,494

New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

04/23/2018

New York  
Motor Vehicle Dept.  
Rochester, NY

**Registration issued or renewed**  
- Titled or registered as personal vehicle  
- Passed safety inspection

11/16/2018 69,731

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**  
- Headlight bulb(s) replaced  
- Oil and filter changed  
- Tire condition and pressure checked  
- Four tires balanced  
- Tires rotated

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

04/15/2019

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**  
- 60,000 mile service performed  
- Wiper(s) replaced  
- Battery/charging system checked  
- Air filter replaced  
- Oil and filter changed

★ 4.9 / 5.0

167 Verified Reviews  
♥ 7 Customer Favorites

- Brake fluid flushed/changed
- Tire(s) balanced
- Tire pressure sensor reprogrammed
- Emissions or safety inspection performed

04/15/2019

New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

05/13/2019 70,327

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**  
- Maintenance inspection completed

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

05/14/2020

New York  
Motor Vehicle Dept.  
Rochester, NY

**Registration issued or renewed**  
- Titled or registered as personal vehicle  
- Passed safety inspection

05/16/2020 79,234

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**  
- Maintenance inspection completed  
- Two tires balanced  
- Tires rotated  
- Oil and filter changed  
- Rear brake pads replaced  
- Rear brake rotor(s) replaced  
- Tire pressure monitoring system reset  
- Battery replaced

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

05/18/2020

New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

10/03/2020 81,245

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**  
- Maintenance inspection completed  
- Four tires balanced  
- Four tires mounted  
- Four wheel alignment performed  
- Drivability/performance checked  
- Ball joint(s) replaced  
- Tires rotated  
- Tire(s) replaced

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

12/04/2020 81,865

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

05/28/2021 83,544

Van Bortel Subaru  
Victor, NY



**Vehicle serviced**  
- Maintenance inspection completed

585-924-5230  
vanbortelsubaru.com  
★ 4.9 / 5.0  
167 Verified Reviews  
❤️ 7 Customer Favorites

- Oil and filter changed

05/29/2021 83,546

New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

12/27/2021 88,588

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.9 / 5.0  
167 Verified Reviews  
❤️ 7 Customer Favorites



**Vehicle serviced**  
- Maintenance inspection completed  
- Air filter replaced  
- Tires rotated  
- Oil and filter changed  
- Cabin air filter replaced/cleaned

02/23/2022 89,252

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.9 / 5.0  
167 Verified Reviews  
❤️ 7 Customer Favorites



**Vehicle serviced**  
- Maintenance inspection completed  
- Four wheel alignment performed  
- Drivability/performance checked  
- Alignment performed

05/03/2022

New York  
Motor Vehicle Dept.  
Rochester, NY

**Registration issued or renewed**  
- Titled or registered as personal vehicle  
- Passed safety inspection

05/31/2022 91,467

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.9 / 5.0  
167 Verified Reviews  
❤️ 7 Customer Favorites



**Vehicle serviced**  
- Emissions or safety inspection performed

05/31/2022

New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

06/01/2023 98,237

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.9 / 5.0  
167 Verified Reviews  
❤️ 7 Customer Favorites



**Vehicle serviced**  
- Maintenance inspection completed  
- Brake fluid flushed/changed  
- Differential fluid flushed/changed  
- Oil and filter changed  
- Brakes checked  
- Tires rotated  
- Front turn signal/parking bulb(s) replaced  
- Front brake rotor(s) replaced  
- Front brake pads replaced  
- Brake rotor(s) replaced



- Rear brake pads replaced

06/02/2023 98,238

New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

11/08/2023

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

05/21/2024 102,848

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Maintenance inspection completed  
- Oil and filter changed  
- Brake line(s) replaced/repaired  
- Rear wheel bearing(s)/hub(s) replaced  
- Battery replaced  
- Battery/charging system checked

★ 4.9 / 5.0  
167 Verified Reviews  
♥ 7 Customer Favorites

05/22/2024

New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

05/27/2024

New York  
Motor Vehicle Dept.  
Webster, NY

**Registration issued or renewed**  
- Titled or registered as personal vehicle  
- Passed safety inspection

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



## Glossary

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

### Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  [facebook.com/CARFAX](https://facebook.com/CARFAX)

 [@CARFAXinc](https://twitter.com/CARFAXinc)

 About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.  
6/27/24 11:17:39 AM (CDT)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2013 SUBARU OUTBACK vehicle (VIN: 4S4BRBPC6D3203422), which is based on information supplied to CARFAX and available as of 6/27/24 at 12:17 PM (EDT).**

---

**Customer Signature**

**Date**

---

**Dealer Signature**

**Date**