

















Display CARFAX in online listings:


	This report provided free of charge by:	5X TOP-RATED DEALER	 10,226 Customer Favorites
	Van Bortel Ford 71 Marsh Rd East Rochester, NY 14445 585-460-1438	 4.8 / 5.0 1,491 Verified Reviews	

	Vehicle History Report™	US \$44.99
	2012 SUBARU IMPREZA 2.0I SPORT PREMIUM	Accident reported: minor damage
	VIN: JF1GPAL63CH228747 WAGON 4 DR 2.0L H4 F SOHC 16V GASOLINE ALL WHEEL DRIVE	  MINOR MODERATE SEVERE
	This CARFAX Report Provided by: Van Bortel Ford	 49 Service history records
	 4.8 / 5.0 1,491 Verified Reviews	 2 Previous owners
	 10,226 Customer Favorites	 Personal vehicle
	 132,240 Last reported odometer reading	

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/9/24 at 2:42:33 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

	Accident / Damage History
Not all accidents / issues are reported to CARFAX	
Event 1	
11/13/2017 Accident reported: minor damage with another motor vehicle	 MINOR MODERATE SEVERE
	

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage Accident reported: 11/13/2017.	<input checked="" type="checkbox"/> No Issues Reported	Minor Damage
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2012	2017
Type of owner	Personal	Personal
Estimated length of ownership	4 yrs. 6 mo.	7 yrs. 5 mo.
Owned in the following states/provinces	West Virginia, New York	New York
Estimated miles driven per year	11,939/yr	10,340/yr

Last reported odometer reading

54,724

132,240




**Detailed History****Owner 1**







Purchased: 2012




Low mileage! This owner drove less than the industry average of 15,000 miles per year.













Personal Vehicle
11,939 mi/yr

Date	Mileage	Source	Comments
05/30/2012	3	Larry Myers Subaru Hyundai Bridgeport, WV 304-848-6000 larrymyershyundai.com	Vehicle offered for sale
05/31/2012	7	Larry Myers Subaru Hyundai Bridgeport, WV 304-848-6000 larrymyershyundai.com	Vehicle sold
05/31/2012		Larry Myers Subaru Hyundai Bridgeport, WV 304-848-6000 larrymyershyundai.com	 Vehicle serviced - Pre-delivery inspection completed - Nitrogen fill tires - Fabric protection applied - Paint protection applied - Emissions or safety inspection performed
05/31/2012		Jenkins Subaru, Hyundai Inc Bridgeport, WV 304-848-6000 jenkins.subaru.com/index.htm ★ 4.6 / 5.0 131 Verified Reviews ❤️ 117 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Fabric protection applied - Paint protection applied - Nitrogen fill tires - Oil and filter changed
06/19/2012		West Virginia Motor Vehicle Dept. Alma, WV Title #DH47874	Title issued or updated - First owner reported - Titled or registered as personal vehicle - Loan or lien reported
08/29/2012	10,121	Larry Myers Subaru Hyundai Bridgeport, WV 304-848-6000 larrymyershyundai.com	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated

08/29/2012		Jenkins Subaru, Hyundai Inc Bridgeport, WV 304-848-6000 jenkins.subaru.com/index.htm ★ 4.6 / 5.0 131 Verified Reviews ❤️ 117 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
12/17/2012	20,193	Larry Myers Subaru Hyundai Bridgeport, WV 304-848-6000 larrymyershyundai.com		Vehicle serviced - Maintenance inspection completed - Oil and filter changed
12/17/2012		Jenkins Subaru, Hyundai Inc Bridgeport, WV 304-848-6000 jenkins.subaru.com/index.htm ★ 4.6 / 5.0 131 Verified Reviews ❤️ 117 Customer Favorites		Vehicle serviced - Maintenance inspection completed
12/19/2013	27,811	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 169 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Oil and filter changed - Engine checked - Engine/powertrain computer/module checked
01/15/2014	28,123	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 169 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced
06/10/2014		West Virginia Motor Vehicle Dept. Alma, WV Title #DH47874		Registration issued or renewed - Loan or lien reported
12/12/2014	35,095	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0		Vehicle serviced - 30,000 mile service performed - Oil and filter changed - Tires rotated

169 Verified Reviews

 7 Customer Favorites

05/18/2015	38,031	Jenkins Subaru, Hyundai Inc Bridgeport, WV 304-848-6000 jenkins.subaru.com/index.htm  4.6 / 5.0 131 Verified Reviews  117 Customer Favorites	 Vehicle serviced -Emissions or safety inspection performed
09/04/2015	41,292	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 169 Verified Reviews  7 Customer Favorites	 Vehicle serviced -Oil and filter changed
04/19/2016	47,538	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 169 Verified Reviews  7 Customer Favorites	 Vehicle serviced -Maintenance inspection completed -Oil and filter changed -Tire condition and pressure checked -Wipers/washers checked -Four tires balanced -Tires rotated
05/09/2016	48,383	Jenkins Subaru, Hyundai Inc Bridgeport, WV 304-848-6000 jenkins.subaru.com/index.htm  4.6 / 5.0 131 Verified Reviews  117 Customer Favorites	 Vehicle serviced -Emissions or safety inspection performed
06/29/2016		West Virginia Motor Vehicle Dept. Alma, WV Title #DH47874	Registration issued or renewed - Loan or lien reported -Registration updated when owner moved the vehicle to a new location
01/03/2017	54,407	New York Inspection Station	Passed safety inspection -Passed emissions inspection
01/03/2017		New York Motor Vehicle Dept. West Henrietta, NY	Registration issued or renewed - Titled or registered as personal vehicle -Passed safety inspection

01/17/2017 54,724 Van Bortel Subaru
 Victor, NY
 585-924-5230
 vanbortelsubaru.com
 ★ 4.8 / 5.0
 169 Verified Reviews
 ❤️ 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked


Owner 2
 Purchased: 2017



Low mileage! This owner drove less than the industry average of 15,000 miles per year.


Personal Vehicle
 10,340 mi/yr

Date	Mileage	Source	Comments
01/17/2017		New York Motor Vehicle Dept. West Henrietta, NY	Title issued or updated - New owner reported
07/26/2017	60,481	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 169 Verified Reviews ❤️ 7 Customer Favorites	Vehicle serviced - Maintenance inspection completed - 60,000 mile service performed - Battery/charging system checked - Air filter replaced - Oil and filter changed - Brake fluid flushed/changed - Tire(s) balanced - Tire pressure sensor reprogrammed
08/03/2017	60,683	Lewis General Tires Inc. Rochester, NY 585-334-0900 ★ 4.9 / 5.0 126 Verified Reviews ❤️ 33 Customer Favorites	Vehicle serviced - One tire mounted - Tire(s) replaced - Tire(s) mounted - Tire(s) dismounted - Tire condition and pressure checked
11/13/2017		Damage Report	Accident reported: minor damage with another motor vehicle - Damage to left side - Damage to left front



Damage Location

FRONT



CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

12/15/2017

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

169 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Battery/charging system checked
- Brakes checked
- Tire condition and pressure checked
- Battery replaced

02/02/2018 65,179

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

169 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Safety inspection performed
- Emissions inspection performed

02/02/2018

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

04/17/2018 66,971

Lewis General Tires Inc.
Rochester, NY
585-334-0900


★ 4.9 / 5.0











126 Verified Reviews









Vehicle serviced

- Tires rotated

 **33** Customer Favorites

07/05/2018	70,653	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 169 Verified Reviews  7 Customer Favorites	 Vehicle serviced - Brakes checked - Oil and filter changed - Front brake rotor(s) replaced - Front brake pads replaced - Rear brake pads replaced - Tire condition and pressure checked - Cabin air filter replaced/cleaned
08/17/2018	73,115	Lewis General Tires Inc. Rochester, NY 585-334-0900 ★ 4.9 / 5.0 126 Verified Reviews  33 Customer Favorites	 Vehicle serviced - Tires rotated
12/19/2018		New York Motor Vehicle Dept. West Henrietta, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
12/20/2018	78,749	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 151 Verified Reviews  15 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Emissions or safety inspection performed
12/20/2018		New York Inspection Station	Passed safety inspection - Passed emissions inspection
01/25/2019	80,221	Lewis General Tires Inc. Rochester, NY 585-334-0900 ★ 4.9 / 5.0 126 Verified Reviews  33 Customer Favorites	 Vehicle serviced - Tires rotated
03/12/2019	81,816	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 151 Verified Reviews  15 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked

06/11/2019	84,666	Lewis General Tires Inc. Rochester, NY 585-334-0900 ★ 4.9 / 5.0 126 Verified Reviews ♥ 33 Customer Favorites		Vehicle serviced - One tire mounted - Tire(s) replaced - Tire(s) mounted - Tire(s) dismounted
07/09/2019	85,236	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 151 Verified Reviews ♥ 15 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Air filter replaced - Oil and filter changed - Brake light switch replaced - Cabin air filter replaced/cleaned
08/27/2019	87,410	Lewis General Tires Inc. Rochester, NY 585-334-0900 ★ 4.9 / 5.0 126 Verified Reviews ♥ 33 Customer Favorites		Vehicle serviced - Tires rotated
10/29/2019	90,526	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 151 Verified Reviews ♥ 15 Customer Favorites		Vehicle serviced - ABS system checked - Oil and filter changed - Valve body replaced
12/09/2019		Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 151 Verified Reviews ♥ 15 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Tire condition and pressure checked - Wipers/washers checked - Sway bar link(s) replaced - Emissions or safety inspection performed
12/09/2019	91,567	New York Inspection Station		Passed safety inspection - Passed emissions inspection
07/17/2020	94,931	Monro Auto Service & Tire Centers Rochester, NY 585-424-3630		Vehicle serviced - Maintenance inspection completed - Exhaust repaired - Exhaust system checked

monro.com

★ 4.6 / 5.0

35 Verified Reviews

08/14/2020 95,457

Lewis General Tires Inc.
Rochester, NY
585-334-0900



Vehicle serviced

- Tires rotated

★ 4.9 / 5.0

126 Verified Reviews

♥ 33 Customer Favorites

10/09/2020 96,588

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/



Vehicle serviced

- Inspection performed
- Tire checked
- Maintenance inspection completed
- Air filter replaced
- Oil and filter changed
- Rear brakes replaced
- Rear brake pads replaced
- Rear brake rotor(s) replaced
- Cabin air filter replaced/cleaned

★ 4.8 / 5.0

151 Verified Reviews

♥ 15 Customer Favorites

11/20/2020 97,582

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/



Vehicle serviced

- Battery serviced
- Battery/charging system checked
- Alignment checked
- Emissions or safety inspection performed

★ 4.8 / 5.0

151 Verified Reviews

♥ 15 Customer Favorites

11/20/2020

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

12/17/2020

New York
Motor Vehicle Dept.
West Henrietta, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

04/16/2021 101,286

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/



Vehicle serviced

- Maintenance inspection completed
- Front wiper blades/refills replaced
- Tires rotated
- Oil and filter changed
- Drive belt(s) replaced
- Brakes checked

★ 4.8 / 5.0

151 Verified Reviews

♥ 15 Customer Favorites

05/29/2021 102,934

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502



Vehicle serviced

- Brakes checked
- Front brake rotor(s) replaced
- Front brake pads replaced

vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

151 Verified Reviews

♥ 15 Customer Favorites

- Front brake caliper(s) replaced
- A/C refrigerant recharged

11/23/2021 107,847

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

151 Verified Reviews

♥ 15 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Two tires balanced
- Tires rotated
- Oil and filter changed
- Tire pressure monitoring system reset

11/23/2021

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

02/18/2022 110,110

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

151 Verified Reviews

♥ 15 Customer Favorites



Vehicle serviced

- Maintenance inspection completed

06/02/2022 112,408

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

151 Verified Reviews

♥ 15 Customer Favorites



Vehicle serviced

- Wheel bearings checked
- Oil and filter changed
- Rear wheel bearing(s)/hub(s) replaced

08/11/2022 114,763

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

151 Verified Reviews

♥ 15 Customer Favorites



Vehicle serviced

- Tire condition and pressure checked
- Oil level sensor replaced
- Oil and filter changed

11/14/2022 116,529

Lewis General Tires Inc.
Rochester, NY
585-334-0900



Vehicle serviced

- One tire mounted
- Tire(s) replaced

★ 4.9 / 5.0

126 Verified Reviews

♥ 33 Customer Favorites

- Tire(s) mounted
- Tire(s) dismounted

11/29/2022 117,071

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

151 Verified Reviews

♥ 15 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Ball joint(s) replaced
- Wiper(s) replaced
- Safety inspection performed
- Emissions or safety inspection performed

11/29/2022

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

12/16/2022

New York
Motor Vehicle Dept.
West Henrietta, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

03/13/2023 119,821

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

151 Verified Reviews

♥ 15 Customer Favorites



Vehicle serviced

- Oil and filter changed
- Rear brake pads replaced
- Rear brake rotor(s) replaced
- Brakes checked

03/24/2023 120,189

Monro Auto Service &
Tire Centers
Rochester, NY
585-424-3630
monro.com

★ 4.6 / 5.0

35 Verified Reviews



Vehicle serviced

- Maintenance inspection completed
- Exhaust repaired
- Exhaust system checked

06/20/2023 122,311

Lewis General Tires Inc.
Rochester, NY
585-334-0900

★ 4.9 / 5.0

126 Verified Reviews

♥ 33 Customer Favorites



Vehicle serviced

- Tires rotated

08/11/2023 124,569

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/



Vehicle serviced

- Maintenance inspection completed
- Differential fluid flushed/changed
- Brake fluid flushed/changed
- Air filter replaced
- Two tires balanced

★ 4.8 / 5.0
151 Verified Reviews
♥ 15 Customer Favorites

- Tires rotated
- Oil and filter changed
- Wheel bearing(s)/hub(s) replaced
- Rear wheel bearing(s)/hub(s) replaced
- Spark plug(s) replaced
- Tire pressure monitoring system reset
- Antifreeze/coolant flushed/changed

11/21/2023 125,862 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/



Vehicle serviced

- Front wiper blades/refills replaced
- Oil and filter changed
- Light bulb(s) replaced

★ 4.8 / 5.0
151 Verified Reviews
♥ 15 Customer Favorites

11/21/2023 New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

02/06/2024 129,183 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/



Vehicle serviced

- Maintenance inspection completed
- Light bulb(s) replaced

★ 4.8 / 5.0
151 Verified Reviews
♥ 15 Customer Favorites

02/26/2024 129,520 Lewis General Tires Inc.
Rochester, NY
585-334-0900



Vehicle serviced

- Tires rotated
- Exhaust repaired

★ 4.9 / 5.0
126 Verified Reviews
♥ 33 Customer Favorites

07/02/2024 132,240 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed

★ 4.8 / 5.0
151 Verified Reviews
♥ 15 Customer Favorites

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/9/24 at 2:42:33 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX

 [@CARFAXinc](https://twitter.com/CARFAXinc)

 [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
7/9/24 2:42:33 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2012 SUBARU IMPREZA vehicle (VIN: JF1GPAL63CH228747), which is based on information supplied to CARFAX and available as of 7/9/24 at 3:42 PM (EDT).

Customer Signature

Date

Dealer Signature

Date