

	Vehicle History Report [™]	US \$44.99				
2015 SUBARU IMPREZA 2.0I LIMITED VIN: JF1GPAM6XFH236458 WAGON 4 DR 2.0L H4 F SOHC 16V GASOLINE ALL WHEEL DRIVE This CARFAX Report Provided by: Van Bortel Ford ★ 4.8 / 5.0 1,485 Verified Reviews ♥ 10,210 Customer Favorites	Accident reported					
	19 Service history records					
	CARFAX 1-Owner vehicle					
	Personal vehicle					
	C Last owned in New York					
	00월 48,044 Last reported odometer reading					

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/27/24 at 11:18:18 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

01/26/2018

Accident reported with another motor vehicle



Not all accidents / issues are reported to CARFAX

Total Loss	No Issues
No total loss reported to CARFAX.	Reported
Structural Damage	No Issues
CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	Reported
Airbag Deployment	No Issues
No airbag deployment reported to CARFAX.	Reported
Odometer Check	No Issues
No indication of an odometer rollback.	Indicated
Accident / Damage Accident reported: 01/26/2018.	Accident Reported
Manufacturer Recall	No Recalls
Check with an authorized Subaru dealer for any open recalls.	Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired
CARFAX Title History CARFAX guarantees the information in this section	Owner 1

Guaranteed

No Problem

Guaranteed

No Problem

~

 \checkmark

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms | View Certificate

CARFAX Ownership History The number of owners is estimated	Owner 1
Year purchased	2015
Type of owner	Personal
Estimated length of ownership	9 yrs. 1 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	5,253/yr
Last reported odometer reading	48,044
CARFAX Detailed History	1

Owner 1 Purchase	ed: 2015		Low mileage! This than the industry miles per year.			Personal Vehicle 5,253 mi/yr
Date	Mileage	Source			Comments	
03/18/2015		Victor, N 585-924- vanborte † 4.9 / 9 167 Verifie	-5230 Isubaru.com		Vehicle offered	d for sale
03/28/2015	9	Victor, N 585-924- vanborte † 4.9 / 1 167 Verifie	-5230 Isubaru.com	×	- Safety inspec	ed hspection completed tion performed safety inspection
04/01/2015	12	New Yor Inspectio	k on Station		Passed safety - Emissions ins	inspection spection performed
04/17/2015		Victor, N 585-924- vanborte † 4.9 / 1 167 Verifie	-5230 Isubaru.com		Vehicle sold	
05/08/2015		New Yor Motor Ve Rocheste	ehicle Dept.		- First owner re	ssued or renewed ported tered as personal vehicle
12/23/2015	1,436	Victor, N 585-924- vanborte 1 67 Verifie	-5230 Isubaru.com	×	Vehicle service	
02/11/2016	2,319	Garber C Webster Webster,		×	Vehicle service	ed

		585-671-5390 garberwebster.com 4.8 / 5.0 339 Verified Reviews 5,762 Customer Favorites		
04/30/2016	3,270	Monro Auto Service & Tire Centers Penfield, NY	×	Vehicle serviced - Emissions inspection performed
04/30/2016		New York Inspection Station		Passed safety inspection - Emissions inspection performed
03/28/2017		New York Motor Vehicle Dept. Rochester, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
06/23/2017	7,457	Monro Auto Service & Tire Centers Rochester, NY 4.6 / 5.0 58 Verified Reviews 1 Customer Favorite	×	Vehicle serviced - Emissions inspection performed
06/23/2017		New York Inspection Station		Passed safety inspection - Passed emissions inspection
09/26/2017	8,598	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.9 / 5.0 167 Verified Reviews 7 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked
11/21/2017	9,760	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ♥ 7 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Tire condition and pressure checked - One tire mounted - Tire(s) replaced - One tire replaced
01/26/2018		Damage Report	•	Accident reported with another motor vehicle
03/12/2018	14,326	Inspection Co.		Inspection performed
10/01/2018	15,370	New York		Passed safety inspection

		Inspection Station		-Passed emissions inspection
03/06/2019	16,718	Monro Auto Service & Tire Centers Rochester, NY 585-442-2780 monro.com	×	Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Tire(s) replaced - Tire(s) mounted - Tire repaired - Tire(s) balanced
03/13/2019		New York Motor Vehicle Dept. Rochester, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
03/29/2019	17,550	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ♥ 7 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated - Tire pressure monitoring system reset
06/06/2019	20,027	Monro Auto Service & Tire Centers Rochester, NY 585-442-2780 monro.com	×	Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Tire(s) replaced - Tire(s) mounted
10/25/2019	26,004	Monro Auto Service & Tire Centers Rochester, NY 585-442-2780 monro.com	×	Vehicle serviced - Recommended maintenance performed - Maintenance inspection completed - Exterior lights checked - Tire condition and pressure checked - Wiper(s) replaced - Battery/charging system checked - Wipers/washers checked - Antifreeze/coolant flushed/changed - Emissions inspection performed
10/25/2019		New York Inspection Station		Passed safety inspection - Passed emissions inspection
08/13/2020		Monro Auto Service & Tire Centers Penfield, NY 585-377-7970 monro.com 4.5 / 5.0	×	Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Brake rotor(s) replaced - Brakes serviced

		32 Verified Reviews 1 Customer Favorite		- Brake rotor(s) resurfaced - Brake pads replaced
09/23/2020	32,111	Monro Auto Service & Tire Centers Penfield, NY 585-377-7970 monro.com ★ 4.5 / 5.0 32 Verified Reviews ♥ 1 Customer Favorite	×	Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Tire pressure monitoring system serviced - Tire(s) replaced - Light bulb(s) replaced - Tire pressure monitoring system checked - Lights checked
11/14/2020	32,783	Monro Auto Service & Tire Centers Penfield, NY 585-377-7970 monro.com ★ 4.5 / 5.0 32 Verified Reviews ♥ 1 Customer Favorite	×	Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Light bulb(s) replaced - Lights checked - Emissions inspection performed
11/14/2020		New York Inspection Station		Passed safety inspection - Passed emissions inspection
03/09/2021		New York		Deviation issued as renewed
00,00,2021		Motor Vehicle Dept. Rochester, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
07/30/2022	36,964	Motor Vehicle Dept.	×	- Titled or registered as personal vehicle
	36,964 36,965	Motor Vehicle Dept. Rochester, NY Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews	×	 Titled or registered as personal vehicle Passed safety inspection Vehicle serviced Maintenance inspection completed Tires rotated Oil and filter changed Four wheel alignment performed Alignment performed
07/30/2022 07/30/2022		Motor Vehicle Dept. Rochester, NY Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ▼ 7 Customer Favorites New York	×	 Titled or registered as personal vehicle Passed safety inspection Vehicle serviced Maintenance inspection completed Tires rotated Oil and filter changed Four wheel alignment performed Alignment performed Stabilizer bar links replaced Passed safety inspection

		585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ♥ 7 Customer Favorites		 Two tires balanced Tires rotated Oil and filter changed Tire pressure monitoring system reset Brakes checked
09/11/2023	42,145	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.9 / 5.0 167 Verified Reviews 7 Customer Favorites	×	Vehicle serviced - Front brake rotor(s) replaced - Front brake pads replaced - Brake rotor(s) replaced - Rear brake pads replaced - Rear brake rotor(s) replaced
09/11/2023	42,151	New York Inspection Station		Passed safety inspection - Passed emissions inspection
06/06/2024	48,044	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.9 / 5.0 167 Verified Reviews ♥ 7 Customer Favorites	×	Vehicle serviced - Two tires balanced - Tires rotated - Oil and filter changed

CARFAX Glossary

Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/27/24 at 11:18:18 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: 👍 facebook.com/C	ARFAX 😏 @C	ARFAXinc C About CARFAX	
CARFAX DEPENDS ON ITS SOURCES FOR ASSUMED BY CARFAX OR ITS AGENTS FO WARRANTIES, EXPRESS OR IMPLIED, INC PURPOSE.	R ERRORS OR OMISSI	ONS IN THIS REPORT. CARFAX FURTHER	EXPRESSLY DISCLAIMS ALL
© 2024 CARFAX, Inc., part of S&P Global. , 6/27/24 11:18:18 AM (CDT)	All rights reserved.		
		(Vehicle History Report for this 20 ed on information supplied to CAR	
Customer Signature	Date	Dealer Signature	Date