

















Display CARFAX in online listings:


|   |   |  |   |
|---|---|--|---|
|  | This report provided free of charge by:   | <b>5X TOP-RATED DEALER</b>   |  <b>10,226</b><br>Customer Favorites |
|   | <b>Van Bortel Ford</b><br>71 Marsh Rd<br>East Rochester, NY 14445<br>585-460-1438 |  <b>4.8 / 5.0</b><br>1,491 Verified Reviews |   |

|  |   |   |
|--|---|---|
|  <b>Vehicle History Report™</b><br>US \$44.99 | <b>2014 SUBARU FORESTER 2.5I LIMITED</b><br>VIN: JF2SJAHC1EH477802<br>4 DOOR WAGON/SPORT UTILITY<br>2.5L H4 F DOHC 16V GASOLINE<br>ALL WHEEL DRIVE<br>This CARFAX Report Provided by:<br><b>Van Bortel Ford</b><br> <b>4.8 / 5.0</b><br>1,491 Verified Reviews<br> <b>10,226</b> Customer Favorites | <b>Damage reported: minor damage</b><br> <br>MINOR      MODERATE      SEVERE |
|  |  <b>25</b> Service history records   |   |
|  |  <b>2</b> Previous owners   |   |
|  |  Personal vehicle  |   |
|  |  <b>208,567</b> Last reported odometer reading   |   |

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/9/24 at 2:44:40 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

|   |   |
|---|---|
|  <b>Accident / Damage History</b><br>Not all accidents / issues are reported to CARFAX |   |
| Event 1   |   |
| 04/03/2018<br><b>Damage reported: minor damage</b>  | <b>Damage Severity Scale</b><br><br>MINOR      MODERATE      SEVERE |
|    |   |

|  <b>Additional History</b><br>Not all accidents / issues are reported to CARFAX | Owner 1   | Owner 2   |
|---|---|---|
| <b>Total Loss</b><br>No total loss reported to CARFAX.  | <input checked="" type="checkbox"/> No Issues Reported  | <input checked="" type="checkbox"/> No Issues Reported  |
| <b>Structural Damage</b><br>CARFAX recommends that you have this vehicle inspected by a collision repair specialist.  | <input checked="" type="checkbox"/> No Issues Reported  | <input checked="" type="checkbox"/> No Issues Reported  |
| <b>Airbag Deployment</b><br>No airbag deployment reported to CARFAX.  | <input checked="" type="checkbox"/> No Issues Reported  | <input checked="" type="checkbox"/> No Issues Reported  |
| <b>Odometer Check</b><br>No indication of an odometer rollback.   | <input checked="" type="checkbox"/> No Issues Indicated | <input checked="" type="checkbox"/> No Issues Indicated |
| <b>Accident / Damage</b><br>Damage reported: 04/03/2018.  | Minor Damage  | No New Issues Reported                                  |
| <b>Manufacturer Recall</b><br>Check with an authorized Subaru dealer for any open recalls.  | <input checked="" type="checkbox"/> No Recalls Reported | <input checked="" type="checkbox"/> No Recalls Reported |
| <b>Basic Warranty</b><br>Original warranty estimated to have expired.   | Warranty Expired  | Warranty Expired  |

|  <b>Title History</b><br>CARFAX guarantees the information in this section | Owner 1   | Owner 2   |
|---|---|---|
| <b>Damage Brands</b><br>Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon  | <input checked="" type="checkbox"/> <b>Guaranteed</b><br>No Problem | <input checked="" type="checkbox"/> <b>Guaranteed</b><br>No Problem |
| <b>Odometer Brands</b><br>Not Actual Mileage   Exceeds Mechanical Limits  | <input checked="" type="checkbox"/> <b>Guaranteed</b><br>No Problem | <input checked="" type="checkbox"/> <b>Guaranteed</b><br>No Problem |



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

|  <b>Ownership History</b><br>The number of owners is estimated | Owner 1                 | Owner 2      |
|---|-------------------------|--------------|
| Year purchased  | 2013                    | 2019         |
| Type of owner   | Personal                | Personal     |
| Estimated length of ownership   | 5 yrs. 5 mo.            | 5 yrs. 2 mo. |
| Owned in the following states/provinces   | West Virginia, New York | New York     |
| Estimated miles driven per year   | 24,462/yr               | 14,411/yr    |

Last reported odometer reading

133,842




208,567

**Detailed History****Owner 1**

Purchased: 2013

Personal Vehicle

24,462 mi/yr

| Date       | Mileage | Source   | Comments  |
|------------|---------|--|---|
| 09/19/2013 | 2       | Mazda Subaru of Winchester<br>Winchester, VA<br>540-545-8000<br>subaruofwinchester.com<br>★ 4.7 / 5.0<br>60 Verified Reviews | <b>Vehicle offered for sale</b>   |
| 09/19/2013 |         | Mazda Subaru of Winchester<br>Winchester, VA<br>540-545-8000<br>subaruofwinchester.com<br>★ 4.7 / 5.0<br>60 Verified Reviews |  <b>Vehicle serviced</b><br>- Pre-delivery inspection completed<br>- Pinstripe(s) installed<br>- Safety inspection performed<br>- Emissions or safety inspection performed |
| 09/19/2013 | 3       | Virginia Inspection Station  | <b>Passed safety inspection</b>   |
| 09/23/2013 | 20      | Mazda Subaru of Winchester<br>Winchester, VA<br>540-545-8000<br>subaruofwinchester.com<br>★ 4.7 / 5.0<br>60 Verified Reviews | <b>Vehicle sold</b>   |
| 10/23/2013 |         | West Virginia Motor Vehicle Dept.<br>Berkeley Springs, WV<br>Title #DR59297  | <b>Registration issued or renewed</b><br>- First owner reported<br>- Titled or registered as personal vehicle   |
| 10/30/2013 | 3,022   | Mazda Subaru of Winchester<br>Winchester, VA<br>540-545-8000<br>subaruofwinchester.com<br>★ 4.7 / 5.0<br>60 Verified Reviews |  <b>Vehicle serviced</b><br>- Oil and filter changed<br>- Maintenance reminder reset<br>- Tire condition and pressure checked<br>- Vehicle washed/detailed               |
| 12/31/2013 | 7,612   | Mazda Subaru of Winchester   |  <b>Vehicle serviced</b><br>- 7,500 mile service performed   |

Winchester, VA  
540-545-8000  
subaruofwinchester.com

★ 4.7 / 5.0  
60 Verified Reviews

04/04/2014 14,576

Mazda Subaru of  
Winchester  
Winchester, VA  
540-545-8000  
subaruofwinchester.com



**Vehicle serviced**

- Maintenance inspection completed
- Drivability/performance checked
- Alignment checked
- Alignment performed

★ 4.7 / 5.0  
60 Verified Reviews

07/23/2014 21,943

Mazda Subaru of  
Winchester  
Winchester, VA  
540-545-8000  
subaruofwinchester.com



**Vehicle serviced**

- Maintenance inspection completed
- Battery/charging system checked
- Alignment checked

★ 4.7 / 5.0  
60 Verified Reviews

08/22/2014

West Virginia  
Motor Vehicle Dept.  
Berkeley Springs, WV  
Title #DR59297

**Registration issued or renewed**

11/17/2014 29,744

Mazda Subaru of  
Winchester  
Winchester, VA  
540-545-8000  
subaruofwinchester.com



**Vehicle serviced**

- Maintenance inspection completed
- Recommended maintenance performed
- Battery/charging system checked
- Alignment checked
- Fuel system cleaned/serviced
- Induction system serviced

★ 4.7 / 5.0  
60 Verified Reviews

03/25/2015 37,778

Mazda Subaru of  
Winchester  
Winchester, VA  
540-545-8000  
subaruofwinchester.com



**Vehicle serviced**

- Maintenance inspection completed
- Recommended maintenance performed
- Battery/charging system checked
- Alignment checked

★ 4.7 / 5.0  
60 Verified Reviews

05/26/2015 42,698

Mazda Subaru of  
Winchester  
Winchester, VA  
540-545-8000  
subaruofwinchester.com



**Vehicle serviced**

- Maintenance inspection completed
- Alignment checked
- Battery/charging system checked
- Alignment performed

★ 4.7 / 5.0  
60 Verified Reviews

06/26/2015 44,765

Mazda Subaru of  
Winchester



**Vehicle serviced**

- Maintenance inspection completed

Winchester, VA  
540-545-8000  
subaruofwinchester.com

★ 4.7 / 5.0  
60 Verified Reviews

- Battery/charging system checked
- Alignment checked

07/20/2015 46,278

Mazda Subaru of  
Winchester  
Winchester, VA  
540-545-8000  
subaruofwinchester.com

★ 4.7 / 5.0  
60 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Tire pressure sensor replaced

05/04/2016 64,097

Mazda Subaru of  
Winchester  
Winchester, VA  
540-545-8000  
subaruofwinchester.com

★ 4.7 / 5.0  
60 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- 30,000 mile service performed
- Alignment checked
- Battery/charging system checked

08/24/2016

West Virginia  
Motor Vehicle Dept.  
Berkeley Springs, WV  
Title #DR59297

**Registration issued or renewed**

11/26/2016 79,821

Mazda Subaru of  
Winchester  
Winchester, VA  
540-545-8000  
subaruofwinchester.com

★ 4.7 / 5.0  
60 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Rear wheel bearing(s)/hub(s) replaced

05/11/2017 90,358

Mazda Subaru of  
Winchester  
Winchester, VA  
540-545-8000  
subaruofwinchester.com

★ 4.7 / 5.0  
60 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Differential serviced
- Battery/charging system checked

07/12/2017

Jiffy Lube Service Center  
#814  
Winchester, VA  
540-662-7800  
jiffylube.com

♥ 22 Customer Favorites



**Vehicle serviced**

12/07/2017

Jiffy Lube #83  
Fairfax, VA  
703-591-5439



**Vehicle serviced**

jiffylube.com/findlocation/searchresult

★ 4.6 / 5.0

5 Verified Reviews

♥ 18 Customer Favorites

03/20/2018

Jiffy Lube #83  
Fairfax, VA  
703-591-5439  
jiffylube.com/findlocation/searchresult



Vehicle serviced

★ 4.6 / 5.0

5 Verified Reviews

♥ 18 Customer Favorites

04/03/2018



Damage Report



Damage reported: minor damage  
- Damage to front



**CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION**



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

06/13/2018

Jiffy Lube Service Center #814  
Winchester, VA  
540-662-7800  
jiffylube.com



Vehicle serviced

♥ 22 Customer Favorites

|            |         |  |   |
|------------|---------|--|---|
| 08/09/2018 |         | West Virginia<br>Motor Vehicle Dept.<br>Berkeley Springs, WV<br>Title #DR59297 | <b>Registration issued or renewed</b>   |
| 04/01/2019 |         | New York<br>Motor Vehicle Dept.<br>Honeoye Falls, NY                           | <b>Registration issued or renewed</b><br>- Titled or registered as personal vehicle<br>- Passed safety inspection |
| 04/12/2019 | 133,842 | New York<br>Inspection Station   | <b>Passed safety inspection</b><br>- Passed emissions inspection  |





**Owner 2**






Purchased: 2019



**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle  
14,411 mi/yr

| Date       | Mileage | Source   | Comments   |
|------------|---------|--|--|
| 04/16/2019 |         | New York<br>Motor Vehicle Dept.<br>Honeoye Falls, NY   | <b>Title issued or updated</b><br>- New owner reported   |
| 10/15/2019 | 140,890 | Van Bortel Subaru Of<br>Rochester<br>Rochester, NY<br>888-309-5502<br>vanbortelsubarurocheste<br>rsoa.dealer.subaru.com/<br>★ 4.8 / 5.0<br>151 Verified Reviews<br>♥ 15 Customer Favorites |  <b>Vehicle serviced</b><br>- Air filter replaced<br>- Light bulb(s) replaced                      |
| 12/11/2019 | 143,275 | Van Bortel Subaru Of<br>Rochester<br>Rochester, NY<br>888-309-5502<br>vanbortelsubarurocheste<br>rsoa.dealer.subaru.com/<br>★ 4.8 / 5.0<br>151 Verified Reviews<br>♥ 15 Customer Favorites |  <b>Vehicle serviced</b><br>- Brakes checked<br>- Oil and filter changed<br>- Valve body replaced |
| 04/21/2020 | 149,099 | New York<br>Inspection Station   | <b>Passed safety inspection</b><br>- Passed emissions inspection   |
| 04/28/2021 |         | New York<br>Motor Vehicle Dept.<br>Honeoye Falls, NY   | <b>Registration issued or renewed</b><br>- Titled or registered as personal vehicle<br>- Passed safety inspection  |
| 05/14/2021 | 169,259 | New York   | <b>Passed safety inspection</b>  |

|            |         |  |   |   |
|------------|---------|--|---|---|
|            |         | Inspection Station   |   | - Passed emissions inspection   |
| 10/09/2021 | 174,510 | <p>Van Bortel Subaru Of Rochester<br/> Rochester, NY<br/> 888-309-5502<br/> vanbortelsubarurocheste<br/> rsoa.dealer.subaru.com/<br/> ★ 4.8 / 5.0<br/> 151 Verified Reviews<br/> ♥ 15 Customer Favorites</p> |    | <p><b>Vehicle serviced</b><br/> - Maintenance inspection completed<br/> - Battery serviced<br/> - Air filter replaced<br/> - Cabin air filter replaced/cleaned</p>  |
| 01/20/2022 | 175,898 | <p>Van Bortel Subaru Of Rochester<br/> Rochester, NY<br/> 888-309-5502<br/> vanbortelsubarurocheste<br/> rsoa.dealer.subaru.com/<br/> ★ 4.8 / 5.0<br/> 151 Verified Reviews<br/> ♥ 15 Customer Favorites</p> |    | <p><b>Vehicle serviced</b><br/> - Inspection performed<br/> - Tire checked<br/> - Maintenance inspection completed<br/> - Oil and filter changed<br/> - Lower control arm(s) replaced<br/> - Parking assist checked</p> |
| 01/09/2023 | 185,596 | <p>Townline Garage<br/> Honeoye Falls, NY<br/> 585-582-2020<br/> townlinegarage.com/</p>   |    | <p><b>Vehicle serviced</b><br/> - Oil and filter changed</p>  |
| 01/09/2023 |         | <p>New York<br/> Inspection Station</p>  |   | <p><b>Passed safety inspection</b><br/> - Passed emissions inspection</p>   |
| 05/18/2023 |         | <p>New York<br/> Motor Vehicle Dept.<br/> Honeoye Falls, NY</p>  |   | <p><b>Registration issued or renewed</b><br/> - Titled or registered as personal vehicle<br/> - Passed safety inspection</p>  |
| 06/14/2023 | 188,815 | <p>Townline Garage<br/> Honeoye Falls, NY<br/> 585-582-2020<br/> townlinegarage.com/</p>   |  | <p><b>Vehicle serviced</b></p>  |
| 02/24/2024 | 201,256 | <p>Dunn Tire<br/> Rochester, NY<br/> 585-393-1130<br/> dunntire.com/locations/5<br/> 76-jefferson-rd-rochester-<br/> 14623<br/> ★ 4.7 / 5.0<br/> 166 Verified Reviews<br/> ♥ 21 Customer Favorites</p>       |  | <p><b>Vehicle serviced</b><br/> - Oil and filter changed</p>  |
| 02/24/2024 |         | <p>New York<br/> Inspection Station</p>  |   | <p><b>Passed safety inspection</b><br/> - Passed emissions inspection</p>   |



06/24/2024 208,567 Burlington Subaru, Inc.  
Burlington, VT  
802-660-8099  
subaruvt.com/

★ 4.7 / 5.0

639 Verified Reviews

♥ 9,764 Customer Favorites



### Vehicle serviced

- Maintenance inspection completed
- Ball joint(s) replaced
- Drivability/performance checked

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



## Glossary

### Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/9/24 at 2:44:40 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

### Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://www.facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.  
7/9/24 2:44:40 PM (CDT)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2014 SUBARU FORESTER vehicle (VIN: JF2SJAHC1EH477802), which is based on information supplied to CARFAX and available as of 7/9/24 at 3:44 PM (EDT).**

---

**Customer Signature**

**Date**

---

**Dealer Signature**

**Date**