




Display CARFAX in online listings:


	<p>This report provided free of charge by: Van Bortel Ford 71 Marsh Rd East Rochester, NY 14445 585-460-1438</p>	<p>5X TOP-RATED DEALER</p> <p>★ 4.8 / 5.0 1,446 Verified Reviews</p>	<p>♥ 9,927 Customer Favorites</p>
--	---	---	---

	<h2>Vehicle History Report™</h2>	<p>US \$44.99</p>
<p>2017 SUBARU IMPREZA PREMIUM</p>	<p>✓ No accidents or damage reported to CARFAX</p>	
<p>VIN: 4S3GTAB69H3727631 WAGON 4 DR 2.0L H4 F SOHC 16V GASOLINE ALL WHEEL DRIVE</p>	<p>🔧 8 Service history records</p>	
<p>This CARFAX Report Provided by: Van Bortel Ford ★ 4.8 / 5.0 1,446 Verified Reviews ♥ 9,927 Customer Favorites</p>	<p>1 CARFAX 1-Owner vehicle</p>	
	<p>🏠 Personal vehicle</p>	
	<p>🌍 Last owned in New York</p>	
	<p>📊 109,921 Last reported odometer reading</p>	


This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/15/24 at 5:43:44 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.


 Additional History	Owner 1
<p>Not all accidents / issues are reported to CARFAX</p>	
<p>Total Loss No total loss reported to CARFAX.</p>	<p>✓ No Issues Reported</p>
<p>Structural Damage No structural damage reported to CARFAX.</p>	<p>✓ No Issues Reported</p>
<p>Airbag Deployment No airbag deployment reported to CARFAX.</p>	<p>✓ No Issues Reported</p>
<p>Odometer Check No indication of an odometer rollback.</p>	<p>✓ No Issues Indicated</p>










Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

CARFAX Ownership History The number of owners is estimated	Owner 1
Year purchased	2017
Type of owner	Personal
Estimated length of ownership	7 years
Owned in the following states/provinces	New York
Estimated miles driven per year	15,839/yr
Last reported odometer reading	109,921

CARFAX Detailed History			
 Owner 1 Purchased: 2017	Personal Vehicle 15,839 mi/yr		
Date	Mileage	Source	Comments
04/10/2017		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0	Vehicle offered for sale

158 Verified Reviews
 7 Customer Favorites

04/12/2017	5	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Safety inspection performed
04/12/2017		New York Inspection Station	Passed safety inspection - Emissions inspection performed
04/14/2017		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites	Vehicle sold
04/14/2017		New York Motor Vehicle Dept. Honeoye, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
05/15/2017		New York Motor Vehicle Dept. Honeoye, NY	Title issued or updated - First owner reported - Loan or lien reported
02/01/2018		New York Motor Vehicle Dept. Honeoye, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
04/11/2018	17,583	New York Inspection Station	Passed safety inspection - Emissions inspection performed
04/19/2019	33,717	New York Inspection Station	Passed safety inspection - Passed emissions inspection
04/29/2019	34,240	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/  4.8 / 5.0 144 Verified Reviews  15 Customer Favorites	 Vehicle serviced - Rear wheel bearing(s)/hub(s) replaced - Noise checked
01/21/2020	45,083	Van Bortel Subaru Of Rochester Rochester, NY	 Vehicle serviced - Inspection performed - Tire checked

888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

144 Verified Reviews

♥ 15 Customer Favorites

- Engine/powertrain computer/module reprogrammed
- PCV valve replaced
- Cabin air filter replaced/cleaned

01/26/2020

New York
Motor Vehicle Dept.
Honeoye, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

04/10/2020 48,811

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubarurocheste.com



Vehicle serviced

- Emissions or safety inspection performed

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

04/10/2020

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

04/02/2021 63,519

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubarurocheste.com



Vehicle serviced

- Emissions or safety inspection performed

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

04/02/2021

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

01/22/2022

New York
Motor Vehicle Dept.
Honeoye, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

03/23/2022 79,970

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubarurocheste.com



Vehicle serviced

- Maintenance inspection completed
- Ignition coil(s) replaced

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

03/23/2022

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

03/22/2023 97,048

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubarurocheste.com



Vehicle serviced

- Maintenance inspection completed
- Spark plug(s) replaced
- Rear wheel bearing(s)/hub(s) replaced
- Brakes serviced

★ **4.8 / 5.0**
 158 Verified Reviews
 ❤️ 7 Customer Favorites

- Brake fluid flushed/changed
- Air filter replaced
- Tire pressure monitoring system reset
- Brakes checked
- Rear wiper blade replaced
- Wheel bearing(s)/hub(s) replaced
- Cabin air filter replaced/cleaned
- Emissions or safety inspection performed

03/22/2023 97,049 New York
 Inspection Station

Passed safety inspection
 - Passed emissions inspection

01/06/2024 New York
 Motor Vehicle Dept.
 Honeoye, NY

Registration issued or renewed
 - Titled or registered as personal vehicle
 - Passed safety inspection

03/21/2024 Van Bortel Subaru
 Victor, NY
 585-924-5230
 vanbortelsubaru.com



Vehicle serviced
 - Maintenance inspection completed
 - Emissions or safety inspection performed

★ **4.8 / 5.0**
 158 Verified Reviews
 ❤️ 7 Customer Favorites

03/21/2024 109,921 New York
 Inspection Station

Passed safety inspection
 - Passed emissions inspection

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: facebook.com/CARFAX

@CARFAXinc

About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2017 SUBARU IMPREZA vehicle (VIN: 4S3GTAB69H3727631), which is based on information supplied to CARFAX and available as of 4/15/24 at 6:43 AM (EDT).

Customer Signature

Date

Dealer Signature

Date