


Display CARFAX in online listings:




This report provided free of charge by:

Van Bortel Ford
 71 Marsh Rd
 East Rochester, NY 14445
 585-460-1438

5X TOP-RATED DEALER

★ **4.8 / 5.0**
 1,444 Verified Reviews

♥ **9,920**
 Customer Favorites




Vehicle History Report™


US \$44.99

<p>2005 SUBARU OUTBACK 2.5I</p> <p>VIN: 4S4BP61C456339621 WAGON 4 DR 2.5L H4 F SOHC 16V GASOLINE ALL WHEEL DRIVE</p> <p>This CARFAX Report Provided by: Van Bortel Ford ★ 4.8 / 5.0 1,444 Verified Reviews ♥ 9,920 Customer Favorites</p>	<div style="display: flex; align-items: center; margin-bottom: 10px;"> ✓ <p>No accidents or damage reported to CARFAX</p> </div> <div style="display: flex; align-items: center; margin-bottom: 10px;"> 🔧 <p>14 Service history records</p> </div> <div style="display: flex; align-items: center; margin-bottom: 10px;"> 👤 <p>2 Previous owners</p> </div> <div style="display: flex; align-items: center; margin-bottom: 10px;"> 🏠 <p>Personal vehicle</p> </div> <div style="display: flex; align-items: center; margin-bottom: 10px;"> 🌍 <p>Last owned in New York</p> </div> <div style="display: flex; align-items: center;"> 📊 <p>203,094 Last reported odometer reading</p> </div>
---	---




This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/10/24 at 12:05:26 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
<p>Total Loss No total loss reported to CARFAX.</p>	<p>✓ No Issues Reported</p>	<p>✓ No Issues Reported</p>
<p>Structural Damage No structural damage reported to CARFAX.</p>	<p>✓ No Issues Reported</p>	<p>✓ No Issues Reported</p>
<p>Airbag Deployment No airbag deployment reported to CARFAX.</p>	<p>✓ No Issues Reported</p>	<p>✓ No Issues Reported</p>
<p>Odometer Check No indication of an odometer rollback.</p>	<p>✓ No Issues Indicated</p>	<p>✓ No Issues Indicated</p>

Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired




CARFAX Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate		


CARFAX Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2005	2012
Type of owner	Personal	Personal
Estimated length of ownership	7 yrs. 3 mo.	11 yrs. 8 mo.
Owned in the following states/provinces	Ontario, New York	New York
Estimated miles driven per year	18,920/yr	5,669/yr
Last reported odometer reading	140,119	203,094

CARFAX Detailed History			
 Owner 1 Purchased: 2005		Personal Vehicle 18,920 mi/yr	
Date	Mileage	Source	Comments
12/31/2004	8	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0	 Vehicle serviced -Pre-delivery inspection completed

158 Verified Reviews

 7 Customer Favorites

01/18/2005	9	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews  7 Customer Favorites	 Vehicle serviced - Safety inspection performed - Engine block heater installed - Emissions or safety inspection performed
01/18/2005		New York Inspection Station	Emissions inspection performed - Passed safety inspection
01/26/2005		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews  7 Customer Favorites	Vehicle sold
01/27/2005		Ontario Ministry of Transportation	Registration issued or renewed - First owner reported - Passed safety inspection - Vehicle color noted as Blue
12/23/2005	11,184	Ontario Ministry of Transportation Greater Toronto Area	Odometer reading reported - Odometer reported as 18,000 kilometers
12/27/2005		Ontario Ministry of Transportation Greater Toronto Area	Registration issued or renewed - Registered as personal vehicle
11/21/2006	27,011	Ontario Ministry of Transportation	Odometer reading reported - Odometer reported as 43,470 kilometers
12/27/2006		Ontario Ministry of Transportation	Registration issued or renewed - Registered as personal vehicle
11/27/2008	64,001	Ontario Ministry of Transportation	Odometer reading reported - Odometer reported as 103,000 kilometers
12/27/2008		Ontario Ministry of Transportation	Registration issued or renewed - Registered as personal vehicle
12/27/2009		Ontario	Registration issued or renewed

		Ministry of Transportation	- Registered as personal vehicle
01/04/2011	68,350	Ontario Inspection Station Mississauga, ON	Passed emissions inspection - Odometer reported as 109,999 kilometers
01/11/2011	68,972	Ontario Ministry of Transportation	Registration issued or renewed - Registered as personal vehicle - Odometer reported as 111,000 kilometers
12/02/2011	80,778	Ontario Ministry of Transportation	Odometer reading reported - Odometer reported as 130,000 kilometers
12/27/2011		Ontario Ministry of Transportation	Registration issued or renewed - Registered as personal vehicle
02/16/2012	83,336	Ontario Inspection Station Mississauga, ON	Passed emissions inspection - Odometer reported as 134,116 kilometers
05/14/2012		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ❤️ 7 Customer Favorites	Vehicle offered for sale
06/18/2012		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ❤️ 7 Customer Favorites	Vehicle sold
06/21/2012		New York Inspection Station	Passed safety inspection - Passed emissions inspection
06/22/2012	140,119	Valvoline Instant Oil Change Canandaigua, NY 585-394-6370 vioc.com ★ 4.7 / 5.0 201 Verified Reviews ❤️ 182 Customer Favorites	 Vehicle serviced - Oil and filter changed
06/22/2012		New York	Registration issued or renewed

Motor Vehicle Dept.
Pittsford, NY

- Titled or registered as personal vehicle
- Passed safety inspection



Owner 2
Purchased: 2012



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
5,669 mi/yr

Date	Mileage	Source		Comments
08/08/2012		New York Motor Vehicle Dept. Pittsford, NY		Title issued or updated - New owner reported
06/20/2013	144,987	New York Inspection Station		Passed safety inspection - Passed emissions inspection
04/28/2014		New York Motor Vehicle Dept. Pittsford, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
08/14/2014	151,244	New York Inspection Station		Passed safety inspection - Passed emissions inspection
11/21/2014		New York Motor Vehicle Dept. Pittsford, NY		Title issued or updated - Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
09/05/2015	155,672	Dunn Tire Rochester, NY 585-272-0180 dunntire.com ★ 4.3 / 5.0 17 Verified Reviews		Vehicle serviced
09/05/2015		New York Inspection Station		Passed safety inspection - Passed emissions inspection
09/26/2015	156,045	Dunn Tire Rochester, NY 585-272-0180 dunntire.com ★ 4.3 / 5.0 17 Verified Reviews		Vehicle serviced - Tire(s) replaced - Four tires replaced - Alignment checked
05/04/2017		New York Motor Vehicle Dept. Winooski, VT		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection - Registration updated when owner moved the vehicle to a new location
05/05/2017	164,931	Midas South Burlington, VT		Vehicle serviced - Exterior lights checked

802-864-4543
midas.com

★ 4.5 / 5.0

85 Verified Reviews

♥ 92 Customer Favorites

- Valve cover gasket(s) replaced
- Rear strut(s)/insert cartridge(s) replaced
- Exhaust pipe replaced
- Exhaust pipe seal replaced
- Front brake rotor(s) replaced
- Brake pads replaced
- Brake fluid flushed/changed
- Brake line(s) replaced/repared
- Spark plug(s) replaced
- Light bulb(s) replaced
- Engine checked
- Shock absorber(s) replaced
- Strut(s) replaced
- Exhaust system checked
- Brake drum(s) resurfaced
- Brake rotor(s) resurfaced
- Brakes replaced
- Exhaust replaced
- Brake system bled
- Safety inspection performed
- Brakes checked
- Brake fluid checked
- Distributor cap replaced
- Breather filter replaced
- Air filter replaced
- Fuel filter replaced
- PCV valve replaced
- License plate light bulb(s) replaced
- Brake calipers cleaned/serviced
- Brake rotor(s) replaced
- Front brake pads replaced
- Emissions or safety inspection performed

05/05/2017

Vermont
Inspection Station

Emissions inspection waived

04/07/2018 170,297

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Air filter checked
- Sway bar link(s) replaced
- Oil and filter changed
- Wheels checked
- Air filter replaced
- Wiper(s) replaced

04/10/2018

New York
Inspection Station

Passed safety inspection





- Passed emissions inspection




10/12/2018

New York
Motor Vehicle Dept.
Rochester, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection
- Registration updated when owner moved the vehicle to a new location

04/29/2019	180,182	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Emissions or safety inspection performed
04/29/2019	180,183	New York Inspection Station		Passed safety inspection - Passed emissions inspection
05/17/2019	180,590	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 142 Verified Reviews ♥ 15 Customer Favorites		Vehicle serviced - Inspection performed - Tire checked
06/18/2020	185,973	New York Inspection Station		Passed safety inspection - Passed emissions inspection
11/01/2020		New York Motor Vehicle Dept. Rochester, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection - Registration updated when owner moved the vehicle to a new location
04/26/2021	187,669	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Tires rotated - Oil and filter changed - Brakes checked
04/26/2021	187,689	New York Inspection Station		Passed safety inspection - Passed emissions inspection
04/30/2022	190,160	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Tires rotated - Oil and filter changed - Emissions or safety inspection performed
04/30/2022		New York Inspection Station		Passed safety inspection - Passed emissions inspection

10/19/2022		New York Motor Vehicle Dept. Rochester, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
04/27/2023	198,353	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Sway bar link(s) replaced - Two tires balanced - Tires rotated - Tire pressure monitoring system reset - Oil and filter changed - Cabin air filter replaced/cleaned - Emissions or safety inspection performed
04/27/2023		New York Inspection Station		Passed safety inspection - Passed emissions inspection
09/17/2023	203,094	Mr. Tire Auto Service Centers Rochester, NY 585-475-1405 mrtire.com ★ 5.0 / 5.0 42 Verified Reviews ❤️ 3 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Brakes checked - Oil and filter changed - Battery/charging system checked - Tires rotated - Brakes serviced
09/19/2023		Mr. Tire Auto Service Centers Rochester, NY 585-427-0777 mrtire.com		Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Alignment checked - Brakes serviced - Steering/suspension checked - Four wheel alignment performed

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes

all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.

4/10/24 12:05:26 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2005 SUBARU OUTBACK vehicle (VIN: 4S4BP61C456339621), which is based on information supplied to CARFAX and available as of 4/10/24 at 1:05 PM (EDT).

Customer Signature

Date

Dealer Signature

Date