


Display CARFAX in online listings:




This report provided free of charge by:

Van Bortel Ford
71 Marsh Rd
East Rochester, NY 14445
585-460-1438

2022 TOP RATED DEALER







★ **4.8 / 5.0**
1,204 Verified Reviews

♥ **8,738**
Customer Favorites





Vehicle History Report™



US \$44.99


<p>2007 SUBARU OUTBACK 2.5I</p> <p>VIN: 4S4BP61C677319786 WAGON 4 DR 2.5L H4 F SOHC 16V GASOLINE ALL WHEEL DRIVE</p> <p>This CARFAX Report Provided by: Van Bortel Ford</p> <p>★ 4.8 / 5.0 1,204 Verified Reviews ♥ 8,738 Customer Favorites</p>	 No accidents or damage reported to CARFAX
	 28 Service history records
	 CARFAX 1-Owner vehicle
	 Personal vehicle
	 Last owned in New York
	 78,787 Last reported odometer reading




This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/16/23 at 11:48:37 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



 Ownership History The number of owners is estimated	Owner 1
Year purchased	2006
Type of owner	Personal
Estimated length of ownership	16 yrs. 5 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	4,988/yr
Last reported odometer reading	78,787













 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. View Terms View Certificate	





 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

 Detailed History			
 Owner 1 Purchased: 2006		Low mileage! This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 4,988 mi/yr
Date	Mileage	Source	Comments
12/02/2006		New York Inspection Station	Emissions inspection performed - Dealer had vehicle inspected to prepare it for sale - Passed safety inspection






12/04/2006		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites	Vehicle sold
12/04/2006	32	New York Motor Vehicle Dept. Rochester, NY	Title issued or updated - First owner reported - Titled or registered as personal vehicle - Loan or lien reported
01/16/2007		New York Motor Vehicle Dept. Rochester, NY	Title issued or updated
05/14/2007		New York Motor Vehicle Dept. Rochester, NY	Title issued or updated - Registration issued or renewed - Titled or registered as personal vehicle - Loan or lien reported - Passed safety inspection
01/24/2008	6,465	New York Inspection Station	Emissions inspection performed - Passed safety inspection
01/30/2009	17,284	New York Inspection Station	Passed safety inspection - Failed emissions inspection
01/30/2009		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites	 Vehicle serviced - Safety inspection performed - Oil and filter changed - Emissions inspection performed
01/30/2009		New York Inspection Station	Passed emissions inspection
03/20/2009		New York Motor Vehicle Dept. Rochester, NY	Title issued or updated - Registration issued or renewed - Titled or registered as personal vehicle - Loan or lien reported - Passed safety inspection
04/06/2010	24,701	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites	 Vehicle serviced - Oil and filter changed - Safety inspection performed






04/06/2010		New York Inspection Station	Passed safety inspection - Passed emissions inspection
10/21/2010	28,396	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites	 Vehicle serviced - Oil and filter changed - Wiper(s) replaced
12/17/2010	29,505	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites	 Vehicle serviced - Remote start installed
04/22/2011		New York Motor Vehicle Dept. Rochester, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
04/25/2011	31,269	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites	 Vehicle serviced - 30,000 mile service performed - Safety inspection performed
04/26/2011	31,271	New York Inspection Station	Passed safety inspection - Passed emissions inspection
01/21/2012	36,494	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites	 Vehicle serviced - Oil and filter changed - Battery replaced
02/04/2012	36,653	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites	 Vehicle serviced

05/01/2012	37,930	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites</p>	 <p>Vehicle serviced - Oil and filter changed - Safety inspection performed - Emissions inspection performed</p>
05/02/2012		<p>New York Inspection Station</p>	<p>Passed safety inspection - Passed emissions inspection</p>
09/26/2012	41,015	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites</p>	 <p>Vehicle serviced - 7,500 mile service performed - Air filter checked - Front wiper blades/refills replaced - Air filter replaced - Oil and filter changed - Tire condition and pressure checked</p>
04/25/2013		<p>New York Motor Vehicle Dept. Rochester, NY</p>	<p>Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection</p>
05/18/2013	44,269	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites</p>	 <p>Vehicle serviced - 15,000 mile service performed - Oil and filter changed - Safety inspection performed</p>
05/18/2013		<p>New York Inspection Station</p>	<p>Passed safety inspection - Passed emissions inspection</p>
07/27/2013	45,234	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites</p>	 <p>Vehicle serviced - Four wheel alignment performed - Tire(s) balanced - Four tires mounted - Tire(s) mounted - Tire condition and pressure checked</p>
04/05/2014	49,023	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites</p>	 <p>Vehicle serviced - Oil and filter changed - Safety inspection performed - Tire condition and pressure checked - Emissions inspection performed</p>
04/05/2014		<p>New York</p>	<p>Passed safety inspection</p>

		Inspection Station		- Emissions inspection performed
04/21/2015		New York Motor Vehicle Dept. Rochester, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
04/27/2015	55,226	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Drive belt(s) replaced - Oil and filter changed - Wheels checked - Front wiper blades/refills replaced - Safety inspection performed
04/28/2015		New York Inspection Station		Passed safety inspection - Passed emissions inspection
02/17/2016	60,276	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites		Vehicle serviced - Oil and filter changed
05/04/2016	61,176	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked - Safety inspection performed - Four tires balanced - Tires rotated - Emissions inspection performed
05/04/2016	61,178	New York Inspection Station		Passed safety inspection - Passed emissions inspection
04/19/2017		New York Motor Vehicle Dept. Rochester, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
05/02/2017	66,172	New York Inspection Station		Failed safety inspection - Passed safety inspection - Passed emissions inspection
05/02/2017		Monro Auto Service & Tire Centers Rochester, NY ★ 4.6 / 5.0 23 Verified Reviews		Vehicle serviced - Alignment checked - Oil and filter changed - Brakes checked - Tire(s) replaced - Tires rotated - Battery/charging system checked - Four wheel alignment performed

- Steering/suspension checked
- Brakes serviced
- Brake pads replaced
- Emissions inspection performed

06/26/2017	66,314	<p>Monro Auto Service & Tire Centers Rochester, NY</p> <p>★ 4.6 / 5.0 23 Verified Reviews</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> -Tire(s) replaced -Tire valve stem(s)/core(s) replaced -Tire(s) balanced
05/05/2018	69,169	<p>New York Inspection Station</p>		<p>Passed safety inspection</p> <ul style="list-style-type: none"> -Passed emissions inspection
05/06/2018		<p>Monro Auto Service & Tire Centers Rochester, NY</p> <p>★ 4.6 / 5.0 23 Verified Reviews</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> -Tires rotated -Battery/charging system checked -Oil and filter changed -Brakes checked -Brakes serviced -Emissions inspection performed
10/21/2018	71,463	<p>Monro Auto Service & Tire Centers Rochester, NY</p> <p>★ 4.6 / 5.0 23 Verified Reviews</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> -Exhaust system checked -Exhaust repaired
03/25/2019		<p>New York Motor Vehicle Dept. Rochester, NY</p>		<p>Registration issued or renewed</p> <ul style="list-style-type: none"> -Titled or registered as personal vehicle -Passed safety inspection
05/22/2019	73,399	<p>Monro Auto Service & Tire Centers Rochester, NY 585-424-3630 monro.com</p> <p>★ 4.6 / 5.0 23 Verified Reviews</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> -Maintenance inspection completed -Recommended maintenance performed -Air filter replaced -Air filter checked -Emissions inspection performed
05/22/2019		<p>New York Inspection Station</p>		<p>Passed safety inspection</p> <ul style="list-style-type: none"> -Passed emissions inspection
12/09/2019	74,559	<p>Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/</p> <p>★ 4.7 / 5.0 94 Verified Reviews ❤️ 8 Customer Favorites</p>		<p>Vehicle serviced</p> <ul style="list-style-type: none"> -Inspection performed -Tire checked -Maintenance inspection completed -Drive belt(s) replaced

12/12/2019		Service Facility	 Inspection performed - Tire checked
03/07/2020	75,034	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.7 / 5.0 94 Verified Reviews ❤️ 8 Customer Favorites	 Vehicle serviced - Inspection performed - Tire checked - Oil and filter changed
03/24/2020	75,051	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.7 / 5.0 94 Verified Reviews ❤️ 8 Customer Favorites	 Vehicle serviced - Inspection performed - Tire checked - Radiator replaced
07/11/2020	75,118	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.7 / 5.0 94 Verified Reviews ❤️ 8 Customer Favorites	 Vehicle serviced - Inspection performed - Tire checked - Oil and filter changed - Tire(s) replaced
07/11/2020	75,145	New York Inspection Station	Passed safety inspection - Passed emissions inspection
03/31/2021		New York Motor Vehicle Dept. Rochester, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
08/02/2021	76,040	New York Inspection Station	Passed safety inspection - Passed emissions inspection
08/03/2021		Monro Auto Service & Tire Centers Rochester, NY 585-424-3630 monro.com ★ 4.6 / 5.0 23 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Tire condition and pressure checked - Tires rotated - Brakes checked - Battery/charging system checked - Oil and filter changed - Tire(s) balanced

- Brakes serviced
- Emissions inspection performed

06/03/2022 77,492

Monro Auto Service & Tire Centers
Rochester, NY
585-424-3630
monro.com

★ 4.6 / 5.0
23 Verified Reviews



Vehicle serviced

- Maintenance inspection completed
- Tires rotated
- Alignment checked
- Four wheel alignment performed
- Steering/suspension checked
- Stabilizer bar links replaced
- Strut(s) replaced
- Exhaust system checked
- Exhaust repaired

09/12/2022

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

09/13/2022 78,787

Monro Auto Service & Tire Centers
Rochester, NY
585-424-3630
monro.com

★ 4.6 / 5.0
23 Verified Reviews



Vehicle serviced

- Maintenance inspection completed
- Tire(s) replaced
- Tire pressure monitoring system serviced
- Tire pressure monitoring system checked
- Emissions inspection performed

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2023 CARFAX, Inc., part of S&P Global. All rights reserved.
5/16/23 11:48:37 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2007 SUBARU OUTBACK vehicle (VIN: 4S4BP61C677319786), which is based on information supplied to CARFAX and available as of 5/16/23 at 12:48 PM (EDT).

Customer Signature

Date

Dealer Signature

Date