


Display CARFAX in online listings:




This report provided free of charge by:

Van Bortel Ford
 71 Marsh Rd
 East Rochester, NY 14445
 585-460-1438

5X TOP-RATED DEALER

★ **4.8 / 5.0**
 1,438 Verified Reviews

♥ **9,907**
 Customer Favorites




Vehicle History Report™


US \$44.99

<p>2011 SUBARU OUTBACK 2.5I PREMIUM</p> <p>VIN: 4S4BRBCC3B3335587 4 DOOR WAGON/SPORT UTILITY 2.5L H4 F DOHC 16V GASOLINE ALL WHEEL DRIVE This CARFAX Report Provided by: Van Bortel Ford ★ 4.8 / 5.0 1,438 Verified Reviews ♥ 9,907 Customer Favorites</p>	<div style="display: flex; align-items: center; margin-bottom: 10px;"> ✓ <p>No accidents or damage reported to CARFAX</p> </div> <div style="display: flex; align-items: center; margin-bottom: 10px;"> 🔧 <p>39 Service history records</p> </div> <div style="display: flex; align-items: center; margin-bottom: 10px;"> 👤 <p>2 Previous owners</p> </div> <div style="display: flex; align-items: center; margin-bottom: 10px;"> 🏠 <p>Personal vehicle</p> </div> <div style="display: flex; align-items: center; margin-bottom: 10px;"> 🌍 <p>Last owned in New York</p> </div> <div style="display: flex; align-items: center;"> 📊 <p>148,650 Last reported odometer reading</p> </div>
---	---


This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/5/24 at 1:05:16 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
<p>Total Loss No total loss reported to CARFAX.</p>	<p>✓ No Issues Reported</p>	<p>✓ No Issues Reported</p>
<p>Structural Damage No structural damage reported to CARFAX.</p>	<p>✓ No Issues Reported</p>	<p>✓ No Issues Reported</p>
<p>Airbag Deployment No airbag deployment reported to CARFAX.</p>	<p>✓ No Issues Reported</p>	<p>✓ No Issues Reported</p>
<p>Odometer Check No indication of an odometer rollback.</p>	<p>✓ No Issues Indicated</p>	<p>✓ No Issues Indicated</p>

Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate		

CARFAX Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2010	2013
Type of owner	Personal	Personal
Estimated length of ownership	2 yrs. 7 mo.	10 yrs. 10 mo.
Owned in the following states/provinces	New York	New York
Estimated miles driven per year	15,530/yr	9,899/yr
Last reported odometer reading	39,656	148,650

CARFAX Detailed History			
 Owner 1 Purchased: 2010		Personal Vehicle 15,530 mi/yr	
Date	Mileage	Source	Comments
09/20/2010	26	New York Inspection Station	Emissions inspection performed - Dealer had vehicle inspected to prepare it for sale - Passed safety inspection

10/13/2010		New York Motor Vehicle Dept. Alfred, NY	Title issued or updated - Registration issued or renewed - First owner reported - Titled or registered as personal vehicle - Loan or lien reported - Passed safety inspection
11/18/2010		New York Motor Vehicle Dept. Alfred, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
05/12/2011		New York Motor Vehicle Dept. Alfred, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
09/29/2011	16,105	New York Inspection Station	Passed safety inspection - Emissions inspection performed
09/27/2012	31,901	New York Inspection Station	Passed safety inspection - Emissions inspection performed
11/23/2012		New York Motor Vehicle Dept. Alfred, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
04/09/2013	39,656	Service Plan Co. Alfred, NY	Service contract issued
04/26/2013		New York Motor Vehicle Dept. Rochester, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection





Owner 2
Purchased: 2013



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
9,899 mi/yr

Date	Mileage	Source	Comments
05/17/2013		New York Motor Vehicle Dept. Rochester, NY	Title issued or updated - New owner reported
09/18/2013	45,230	New York Inspection Station	Passed safety inspection - Passed emissions inspection
08/06/2014	53,563	Garber Chevrolet Subaru Webster Webster, NY 585-671-5390 garberwebster.com ★ 4.8 / 5.0 331 Verified Reviews	 Vehicle serviced - Service contract claim - Oil and filter changed - Tires rotated - Body water leak checked - Cabin air filter replaced/cleaned

 **5,375** Customer Favorites

09/05/2014 54,518

Garber Chevrolet Subaru Webster
Webster, NY
585-671-5390
garberwebster.com



Vehicle serviced

- Body water leak checked

 **4.8 / 5.0**

331 Verified Reviews

 **5,375** Customer Favorites

09/30/2014

Garber Chevrolet Subaru Webster
Webster, NY
585-671-5390
garberwebster.com



Vehicle serviced

- Emissions or safety inspection performed

 **4.8 / 5.0**

331 Verified Reviews

 **5,375** Customer Favorites

09/30/2014 55,114

New York Inspection Station

Passed safety inspection

- Passed emissions inspection

04/03/2015

New York Motor Vehicle Dept.
Rochester, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

04/25/2015 59,785

Garber Chevrolet Subaru Webster
Webster, NY
585-671-5390
garberwebster.com



Vehicle serviced

- Maintenance inspection completed

 **4.8 / 5.0**

331 Verified Reviews

 **5,375** Customer Favorites

10/07/2015

Garber Chevrolet Subaru Webster
Webster, NY
585-671-5390
garberwebster.com




Vehicle serviced

- Oil and filter changed
- Cabin air filter replaced/cleaned
- Transmission fluid flushed
- Emissions or safety inspection performed

 **4.8 / 5.0**

331 Verified Reviews

 **5,375** Customer Favorites

10/07/2015 64,284

New York Inspection Station

Passed safety inspection

- Passed emissions inspection

06/24/2016 71,146

Garber Chevrolet Subaru Webster



Vehicle serviced

Webster, NY
585-671-5390
garberwebster.com

★ 4.8 / 5.0

331 Verified Reviews
Customer Favorites
♥ 5,375

08/01/2016 72,626

Garber Chevrolet Subaru
Webster
Webster, NY
585-671-5390
garberwebster.com



Vehicle serviced

★ 4.8 / 5.0

331 Verified Reviews
Customer Favorites
♥ 5,375

10/24/2016 75,444

Garber Chevrolet Subaru
Webster
Webster, NY
585-671-5390
garberwebster.com



Vehicle serviced

- Emissions or safety inspection performed

★ 4.8 / 5.0

331 Verified Reviews
Customer Favorites
♥ 5,375

10/24/2016

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

12/08/2016 76,826

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked
- Headlight bulb(s) replaced

★ 4.8 / 5.0

158 Verified Reviews
Customer Favorites
♥ 7

03/21/2017 79,287

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Oil and filter changed
- Tire condition and pressure checked
- Body lubricated

★ 4.8 / 5.0

158 Verified Reviews
Customer Favorites
♥ 7

03/28/2017

New York
Motor Vehicle Dept.
Rochester, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

06/30/2017 81,702

Van Bortel Subaru
Victor, NY
585-924-5230



Vehicle serviced

- Maintenance inspection completed
- Air filter replaced

vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

- Battery replaced
- Cabin air filter replaced/cleaned

09/06/2017 84,237

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Body lubricated

10/20/2017 86,108

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Safety inspection performed
- Emissions inspection performed

10/20/2017

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

11/14/2017 86,993

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Headlight bulb(s) replaced

01/02/2018 89,178

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked
- Front turn signal/parking bulb(s) replaced

03/07/2018 90,325

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Oil and filter changed
- Tire condition and pressure checked
- Body lubricated
- Cabin air filter replaced/cleaned

07/05/2018 93,518

Van Bortel Subaru
Victor, NY
585-924-5230



Vehicle serviced

- Oil and filter changed
- Light bulb(s) replaced

vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

- Front brake pads replaced
- Wheel bearing(s)/hub(s) replaced
- Rear wheel bearing(s)/hub(s) replaced
- Tire condition and pressure checked
- Body lubricated

10/25/2018 96,324

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Brakes checked
- Ball joint(s) replaced
- Front brakes serviced
- Emissions or safety inspection performed

10/25/2018

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

02/11/2019 99,102

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

142 Verified Reviews

♥ 15 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Tire condition and pressure checked
- Wipers/washers checked
- Brake light bulb(s) replaced
- Oil and filter changed
- Lower ball joint(s) replaced
- Front brake rotor(s) replaced
- Front brake pads replaced

03/15/2019

New York
Motor Vehicle Dept.
Rochester, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

09/16/2019 105,409

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

142 Verified Reviews

♥ 15 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed

09/16/2019 105,411

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

09/27/2019 105,716


Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

142 Verified Reviews




Vehicle serviced

 15 Customer Favorites

10/16/2019 106,415 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

 4.8 / 5.0

142 Verified Reviews

 15 Customer Favorites




Vehicle serviced

- Inspection performed
- Tire checked
- Maintenance inspection completed
- Brakes checked

04/07/2020 110,238 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

 4.8 / 5.0

142 Verified Reviews

 15 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed

05/19/2020 111,015 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

 4.8 / 5.0

142 Verified Reviews

 15 Customer Favorites




Vehicle serviced

08/29/2020 113,657 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

 4.8 / 5.0

142 Verified Reviews

 15 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Four wheel alignment performed
- Oil and filter changed
- Alignment performed
- Control arm bushing(s) replaced

08/31/2020 New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

10/16/2020 115,266 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

 4.8 / 5.0

















Vehicle serviced


- Maintenance inspection completed
- Cabin air filter replaced/cleaned







142 Verified Reviews

 15 Customer Favorites

03/19/2021		New York Motor Vehicle Dept. Rochester, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
04/19/2021	119,112	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 142 Verified Reviews  15 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Air filter replaced - Spark plug(s) replaced - Differential fluid flushed/changed - Brake fluid flushed/changed
05/03/2021	119,275	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 142 Verified Reviews  15 Customer Favorites		Vehicle serviced - Vehicle washed/detailed
06/05/2021	119,777	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 142 Verified Reviews  15 Customer Favorites		Vehicle serviced - Rear wiper blade replaced
08/28/2021	122,439	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Oil and filter changed - Cabin air filter replaced/cleaned - Emissions or safety inspection performed
08/28/2021	122,441	New York Inspection Station		Passed safety inspection - Passed emissions inspection
09/01/2021		Service Facility		Vehicle reconditioned

09/27/2021	123,188	<p>Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/</p> <p>★ 4.8 / 5.0 142 Verified Reviews ♥ 15 Customer Favorites</p>	 <p>Vehicle serviced - Brakes checked</p>
03/31/2022	127,798	<p>Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/</p> <p>★ 4.8 / 5.0 142 Verified Reviews ♥ 15 Customer Favorites</p>	 <p>Vehicle serviced - Maintenance inspection completed - Oil and filter changed</p>
08/31/2022	133,119	<p>Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/</p> <p>★ 4.8 / 5.0 142 Verified Reviews ♥ 15 Customer Favorites</p>	 <p>Vehicle serviced - Maintenance inspection completed - Air filter replaced - Oil and filter changed - Cabin air filter replaced/cleaned - Emissions or safety inspection performed</p>
09/01/2022		<p>New York Inspection Station</p>	<p>Passed safety inspection - Passed emissions inspection</p>
10/03/2022	134,146	<p>Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/</p> <p>★ 4.8 / 5.0 142 Verified Reviews ♥ 15 Customer Favorites</p>	 <p>Vehicle serviced - Brakes checked</p>
01/05/2023	136,954	<p>Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/</p> <p>★ 4.8 / 5.0 142 Verified Reviews</p>	 <p>Vehicle serviced - Ball joint(s) replaced - Oil and filter changed - Front brake pads replaced</p>

 15 Customer Favorites

03/26/2023		New York Motor Vehicle Dept. Rochester, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
06/16/2023	140,689	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 142 Verified Reviews  15 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Rear brakes replaced - Oil and filter changed - Drivability/performance checked - Wiper(s) replaced - Brakes checked - Rear brake pads replaced
09/27/2023	144,488	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 142 Verified Reviews  15 Customer Favorites		Vehicle serviced - Front wheel bearing(s)/hub(s) replaced - Fog lights installed
09/28/2023	144,491	New York Inspection Station		Passed safety inspection - Passed emissions inspection
02/26/2024	148,650	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.8 / 5.0 142 Verified Reviews  15 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire(s) changed - Tire condition and pressure checked - Wheel lug nuts torqued

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
4/5/24 1:05:16 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2011 SUBARU OUTBACK vehicle (VIN: 4S4BRBCC3B3335587), which is based on information supplied to CARFAX and available as of 4/5/24 at 2:05 PM (EDT).

Customer Signature

Date

Dealer Signature

Date