


















Display CARFAX in online listings:


	This report provided free of charge by: Van Bortel Ford 71 Marsh Rd East Rochester, NY 14445 585-460-1438	5X TOP-RATED DEALER  1,446 Verified Reviews	 Customer Favorites
--	--	--	---

	Vehicle History Report™	US \$44.99
2013 SUBARU OUTBACK 3.6R LIMITED VIN: 4S4BRDLC9D2307233 4 DOOR WAGON/SPORT UTILITY 3.6L H6 F DOHC 24V GASOLINE ALL WHEEL DRIVE This CARFAX Report Provided by: Van Bortel Ford  1,446 Verified Reviews 	<ul style="list-style-type: none"> No accidents or damage reported to CARFAX 40 Service history records CARFAX 1-Owner vehicle Personal vehicle Last owned in New York 104,217 Last reported odometer reading	



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/15/24 at 5:42:31 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	 No Issues Reported
Structural Damage No structural damage reported to CARFAX.	 No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	 No Issues Reported
Odometer Check No indication of an odometer rollback.	 No Issues Indicated

Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

CARFAX Ownership History The number of owners is estimated	Owner 1
Year purchased	2013
Type of owner	Personal
Estimated length of ownership	10 yrs. 10 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	10,002/yr
Last reported odometer reading	104,217

CARFAX Detailed History			
 Owner 1 Purchased: 2013		Low mileage! This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 10,002 mi/yr
Date	Mileage	Source	Comments
04/30/2013		Van Bortel Subaru Victor, NY 585-924-5230	Vehicle offered for sale

vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

04/30/2013 357

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Pre-delivery inspection completed
- Body side moldings installed
- Emissions or safety inspection performed

05/06/2013

New York
Inspection Station

Dealer had vehicle inspected to prepare it for sale

- Passed safety inspection
- Emissions inspection performed

05/07/2013

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

Vehicle sold

06/05/2013

New York
Motor Vehicle Dept.
Canandaigua, NY

Title issued or updated

- Registration issued or renewed
- First owner reported
- Titled or registered as personal vehicle
- Loan or lien reported
- Passed safety inspection

08/05/2013 3,828

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Oil and filter changed

11/20/2013 7,245

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites



Vehicle serviced

- Recommended maintenance performed
- Oil and filter changed

02/26/2014 9,992

Van Bortel Subaru
Victor, NY
585-924-5230



Vehicle serviced

- Oil and filter changed

vanbortelsubaru.com

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

05/27/2014 12,756

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Safety inspection performed
- Oil and filter changed

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

05/28/2014

New York
Inspection Station

Passed safety inspection

- Emissions inspection performed

09/10/2014 19,655

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Oil and filter changed

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

01/02/2015

New York
Motor Vehicle Dept.
Canandaigua, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

03/04/2015 25,399

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Oil and filter changed

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

05/30/2015 28,251

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Safety inspection performed
- Emissions or safety inspection performed

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

05/30/2015

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

07/09/2015 29,646

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Recommended maintenance performed
- Rear wiper blade replaced
- Oil and filter changed

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

- Tires rotated

11/03/2015 33,369

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Oil and filter changed
- Cabin air filter replaced/cleaned

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

12/07/2015 34,417

Dunn Tire
Buffalo, NY
585-393-1130
dunntire.com



Vehicle serviced

- Tire(s) replaced
- Four tires replaced

02/15/2016 36,497

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Oil and filter changed

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

05/23/2016 39,662

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Four wheel alignment performed
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked
- Four tires balanced
- Four tires mounted
- Four tires replaced

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

05/24/2016

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

08/16/2016 42,896

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Oil and filter changed
- Tire condition and pressure checked
- Body lubricated

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites


11/29/2016 46,332

















Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

★ 4.8 / 5.0
158 Verified Reviews

 7 Customer Favorites

12/09/2016		New York Motor Vehicle Dept. Canandaigua, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
03/24/2017	49,495	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Oil and filter changed - Tire condition and pressure checked - Body lubricated
04/14/2017	50,245	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked - Tire(s) balanced - Tire(s) mounted - Back-up camera replaced
05/20/2017	51,498	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked - Safety inspection performed - Emissions inspection performed
05/20/2017		New York Inspection Station		Passed safety inspection - Passed emissions inspection
11/20/2017	57,621	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed
03/02/2018	60,393	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Headlight bulb(s) replaced - Cabin air filter replaced/cleaned
04/24/2018	62,143	Van Bortel Subaru Victor, NY		Vehicle serviced - Front wiper blades/refills replaced

585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews
❤️ 7 Customer Favorites

- Four tires mounted
- Rear brake pads replaced
- Rear brake rotor(s) replaced
- Brake rotor(s) replaced
- Front turn signal/parking bulb(s) replaced

05/31/2018 63,054

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews
❤️ 7 Customer Favorites



Vehicle serviced

05/31/2018

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

07/03/2018 64,100

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews
❤️ 7 Customer Favorites



Vehicle serviced

10/29/2018 66,292

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews
❤️ 7 Customer Favorites



Vehicle serviced
- Maintenance inspection completed
- 60,000 mile service performed
- Tire condition and pressure checked
- Headlight bulb(s) replaced
- Battery replaced
- Battery/charging system checked
- Air filter replaced

12/03/2018

New York
Motor Vehicle Dept.
Canandaigua, NY

Registration issued or renewed
- Titled or registered as personal vehicle
- Passed safety inspection

04/15/2019 69,635

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews
❤️ 7 Customer Favorites




Vehicle serviced
- Oil and filter changed
- Tire condition and pressure checked
- Body lubricated
- Cabin air filter replaced/cleaned

















05/31/2019 70,786

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews



Vehicle serviced
- Maintenance inspection completed
- Emissions or safety inspection performed

 7 Customer Favorites

05/31/2019		New York Inspection Station		Passed safety inspection - Passed emissions inspection
09/30/2019	74,407	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Oil and filter changed - Light bulb(s) replaced - Tire condition and pressure checked
12/18/2019	75,977	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked
04/20/2020	78,258	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Tire(s) balanced - Four tires balanced - Four tires mounted - Tire(s) mounted
05/29/2020	78,875	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Emissions or safety inspection performed
05/29/2020		New York Inspection Station		Passed safety inspection - Passed emissions inspection
06/08/2020	79,054	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Maintenance inspection completed
08/12/2020	80,673	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com		Vehicle serviced - Maintenance inspection completed - Oil and filter changed

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

11/03/2020 82,546

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

12/10/2020

New York
Motor Vehicle Dept.
Canandaigua, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

03/25/2021 85,171

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Tire(s) changed
- Tire(s) balanced

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

05/25/2021 86,919

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Emissions or safety inspection performed

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

05/25/2021

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

12/08/2021 91,353

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

05/27/2022 94,275




Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Brakes checked
- Light bulb(s) replaced
- Tire(s) replaced
- Four wheel alignment performed
- Alignment performed

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

05/27/2022		New York Inspection Station		Passed safety inspection - Passed emissions inspection
11/14/2022	97,488	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Air filter replaced - Tire(s) balanced - Tire(s) mounted - Four tires balanced - Brakes checked - Cabin air filter replaced/cleaned
12/30/2022		New York Motor Vehicle Dept. Canandaigua, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
05/23/2023	101,125	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Oil and filter changed - Emissions or safety inspection performed
05/23/2023		New York Inspection Station		Passed safety inspection - Passed emissions inspection
10/05/2023	104,217	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ❤️ 7 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Brake fluid flushed/changed - Differential fluid flushed/changed - Air filter replaced - Oil and filter changed - Engine checked - Engine/powertrain computer/module checked - Four wheel alignment performed - Brake line(s) replaced/repared - Battery/charging system checked - Tire(s) changed - Battery replaced - Alignment performed - Control arm(s) replaced - Engine cradle replaced/repared - Brakes checked

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
4/15/24 5:42:31 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2013 SUBARU OUTBACK vehicle (VIN: 4S4BRDLC9D2307233), which is based on information supplied to CARFAX and available as of 4/15/24 at 6:42 AM (EDT).

Customer Signature

Date

Dealer Signature

Date